

## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** Carol & James Hayes 2253 S 16th Road PO Box 26 Ballantine MT 59006 Phone: (406) 967-2895

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5606325	Tiger Town	2253 S 16th Road	Ballantine	59006	(406) 967-2895

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
9 / 10 Currently In Use	3310	11/1/1992 13 / No	Diesel 3,000	STI-P3 None	Fiberglass Reinforced Plastic Cathodically Protected	Safe Suction	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> D E F G H I J K L</div> </div>	Yes Yes Yes Yes
10 / 11 Currently In Use	3311	11/1/1992 13 / No	Gasoline 4,000	STI-P3 None	Fiberglass Reinforced Plastic Cathodically Protected	Safe Suction	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> D E F G H I J K L</div> </div>	Yes Yes Yes Yes
11 / 12 Currently in Use	3312	11/1/1992 13 / No	Gasoline 5,000	STI-P3 None	Fiberglass Reinforced Plastic Cathodically Protected	Safe Suction	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> D E F G H I J K L</div> </div>	Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** Cenex Petroleum Inc PO Box 64089 MS 535 Saint Paul MN 55164 Phone: (651) 355-5583

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5600050	Kum and Go Store 821	1544 Broadwater Ave	Billings	59102	(406) 651-0001

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
4 / 04 Currently In Use	3074	10/30/1997 08 / No	Gasoline 10,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div>	Yes Yes Yes Yes
5 / 05 Currently In Use	3075	10/30/1997 08 / No	Gasoline 10,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div>	Yes Yes Yes Yes
6 / 06 Currently In Use	3076	10/30/1997 08 / No	Gasoline 15,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div>	Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** Stockton Oil Co 1607 4th Ave N PO Box 1756 Billings MT 59103 Phone: (406) 245-6376

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5600062	Five Corners Quik Stop	5550 Highway 312	Billings	59105	

TankID/Alt TankID	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction	Piping Material		Tank Release Detection	FR Met																								
Status				Secondary Option	Secondary Option	Piping Type	Piping Release Detection	Spill/Overl/C																								
1 / 01 Currently in Use	3673	12/20/1977 28 / No	Gasoline 10,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Fiberglass Reinforced Plastic None	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>●</td><td>J</td><td>K</td><td>L</td></tr><tr><td>B</td><td></td><td></td><td>●</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>●</td><td>K</td><td>L</td></tr></table>	A	B	C	D	E	F	G	H	●	J	K	L	B			●	E	F	G	H	I	●	K	L	No Yes Yes Yes
A	B	C	D	E	F	G	H	●	J	K	L																					
B			●	E	F	G	H	I	●	K	L																					
2 / 02 Currently in Use	3674	12/20/1977 28 / No	Gasoline 10,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Fiberglass Reinforced Plastic None	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>●</td><td>J</td><td>K</td><td>L</td></tr><tr><td>B</td><td></td><td></td><td>●</td><td>E</td><td>F</td><td>G</td><td>H</td><td>●</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	D	E	F	G	H	●	J	K	L	B			●	E	F	G	H	●	J	K	L	No Yes Yes Yes
A	B	C	D	E	F	G	H	●	J	K	L																					
B			●	E	F	G	H	●	J	K	L																					

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** SNG Inc 4410 State Ave Billings MT 59101 Phone: (406) 245-0161

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5600063	3 Gs Convenience Center 3	730 Lake Elmo Dr	Billings	59105	(406) 255-0688

TankID/Alt TankID	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction	Piping Material	Piping Type	Tank Release Detection	FR Met																								
Status				Secondary Option	Secondary Option		Piping Release Detection	Spill/Overl/C																								
1 / 01 Currently in Use	1871	12/20/1984 21 / No	Diesel 10,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Flexible Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td><input checked="" type="radio"/></td><td>J</td><td>K</td><td>L</td></tr><tr><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	D	E	F	G	H	<input checked="" type="radio"/>	J	K	L	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	Yes Yes Yes Yes
A	B	C	D	E	F	G	H	<input checked="" type="radio"/>	J	K	L																					
<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					
2 / 02 Currently in Use	1872	12/20/1984 21 / No	Gasoline 10,000	STI-P3 Impressed Current	Flexible Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td><input checked="" type="radio"/></td><td>J</td><td>K</td><td>L</td></tr><tr><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	D	E	F	G	H	<input checked="" type="radio"/>	J	K	L	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	Yes Yes Yes Yes
A	B	C	D	E	F	G	H	<input checked="" type="radio"/>	J	K	L																					
<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					
3 / 03 Currently in Use	1873	12/20/1984 21 / No	Gasoline 10,000	STI-P3 Impressed Current	Flexible Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td><input checked="" type="radio"/></td><td>J</td><td>K</td><td>L</td></tr><tr><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	D	E	F	G	H	<input checked="" type="radio"/>	J	K	L	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	Yes Yes Yes Yes
A	B	C	D	E	F	G	H	<input checked="" type="radio"/>	J	K	L																					
<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** Rimrock Oldsmobile Suzuki 324 S 24th St W Billings MT 59102 Phone: (406) 656-6200

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5600066	Rimrock Oldsmobile Suzuki	324 S 24th St W	Billings	59102	(406) 656-6200

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
4 / 04 Currently in Use	1863	10/1/1991 14 / No	Gasoline 1,000	STI-P3 None	Fiberglass Reinforced Plastic None	Safe Suction	<div> <input checked="" type="radio"/> A           <input type="radio"/> B           <input type="radio"/> C           <input type="radio"/> D           <input type="radio"/> E           <input type="radio"/> F           <input type="radio"/> G           <input type="radio"/> H           <input type="radio"/> I           <input type="radio"/> J           <input type="radio"/> K           <input type="radio"/> L         </div> <div> <input type="radio"/> D           <input type="radio"/> E           <input type="radio"/> F           <input type="radio"/> G           <input type="radio"/> H           <input type="radio"/> I           <input checked="" type="radio"/> J           <input type="radio"/> K           <input type="radio"/> L         </div>	Yes Yes Yes Yes
5 / 05 Currently in Use	1864	10/1/1991 14 / No	Used Oil 1,000	STI-P3 None	Fiberglass Reinforced Plastic None	Gravity Feed	<div> <input checked="" type="radio"/> A           <input checked="" type="radio"/> B           <input type="radio"/> C           <input type="radio"/> D           <input type="radio"/> E           <input type="radio"/> F           <input type="radio"/> G           <input type="radio"/> H           <input type="radio"/> I           <input type="radio"/> J           <input type="radio"/> K           <input type="radio"/> L         </div> <div> <input checked="" type="radio"/> D           <input type="radio"/> E           <input type="radio"/> F           <input type="radio"/> G           <input type="radio"/> H           <input type="radio"/> I           <input type="radio"/> J           <input type="radio"/> K           <input type="radio"/> L         </div>	Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** Archie Cochrane Motors PO Box 80605 Billings MT 59108 Phone: (406) 656-1100

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5600123	Archie Cochrane Motors	2133 King Ave W	Billings	59102	(406) 656-1100

TankID/Alt TankID	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction	Piping Material		Tank Release Detection	FR Met																								
Status				Secondary Option	Secondary Option	Piping Type	Piping Release Detection	Spill/Overl/C																								
4 / 04 Currently in Use	390	8/1/1993 12 / No	Gasoline 2,000	STI-P3 Double-Walled	Fiberglass Reinforced Plastic None	Safe Suction	<table><tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td>B</td><td></td><td></td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td><input checked="" type="radio"/></td><td>K</td><td>L</td></tr></table>	A	B	C	D	E	F	<input checked="" type="radio"/>	H	I	J	K	L	B			D	E	F	G	H	I	<input checked="" type="radio"/>	K	L	Yes Yes Yes Yes
A	B	C	D	E	F	<input checked="" type="radio"/>	H	I	J	K	L																					
B			D	E	F	G	H	I	<input checked="" type="radio"/>	K	L																					
5 / 05 Currently in Use	391	8/1/1993 12 / No	Diesel 1,000	STI-P3 Double-Walled	Fiberglass Reinforced Plastic None	Safe Suction	<table><tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td>B</td><td></td><td></td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td><input checked="" type="radio"/></td><td>K</td><td>L</td></tr></table>	A	B	C	D	E	F	<input checked="" type="radio"/>	H	I	J	K	L	B			D	E	F	G	H	I	<input checked="" type="radio"/>	K	L	Yes Yes Yes Yes
A	B	C	D	E	F	<input checked="" type="radio"/>	H	I	J	K	L																					
B			D	E	F	G	H	I	<input checked="" type="radio"/>	K	L																					

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** GM Petroleum Dist Inc PO Box 30335 Billings MT 59107 Phone: (406) 252-4661

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5600503	Conomart Superstore 4	1240 S 27th St	Billings	59101	

TankID/Alt TankID	Tag Numbe	Installed	Product	Tank Mat'l of Construction	Piping Material	Piping Type	Tank Release Detection	FR Met																								
Status		Age/AST	Capacity	Secondary Option	Secondary Option		Piping Release Detection	Spill/Overl/C																								
4 / 04 Currently In Use	1148	5/1/1998 08 / No	Gasoline 10,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td></td><td>B</td><td></td><td>D</td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L		B		D	E	F	<input checked="" type="radio"/>	H	I	J	K	L	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L																					
	B		D	E	F	<input checked="" type="radio"/>	H	I	J	K	L																					
5 / 05 Currently In Use	1149	5/1/1998 08 / No	Gasoline 10,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td></td><td>B</td><td></td><td>D</td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L		B		D	E	F	<input checked="" type="radio"/>	H	I	J	K	L	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L																					
	B		D	E	F	<input checked="" type="radio"/>	H	I	J	K	L																					
6 / 06 Currently In Use	1150	5/1/1998 08 / No	Diesel 8,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td></td><td>B</td><td></td><td>D</td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L		B		D	E	F	<input checked="" type="radio"/>	H	I	J	K	L	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L																					
	B		D	E	F	<input checked="" type="radio"/>	H	I	J	K	L																					

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** Pelican Oil Co PO Box 549 Billings MT 59103 Phone: (406) 245-4531

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5600625	Pacific Pride Billings	4840 Laurel Road	Billings	59101	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
1 / 01 Currently in Use	4536	5/3/1971 35 / No	Gasoline 6,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Galvanized Steel Impressed Current	Safe Suction	<div> <div>A B ● D E F G H I J K L</div> <div>B D E F G H I ● K L</div> </div>	Yes Yes Yes Yes
2 / 02 Currently in Use	4537	5/3/1971 35 / No	Gasoline 6,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Galvanized Steel Impressed Current	Safe Suction	<div> <div>A B ● D E F G H I J K L</div> <div>B D E F G H I ● K L</div> </div>	Yes Yes Yes Yes
3 / 03 Currently in Use	4538	5/3/1971 35 / No	Diesel 6,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Galvanized Steel Impressed Current	Pressurized	<div> <div>A B ● D E F G H I J K L</div> <div>● ● E F G H I J K L</div> </div>	Yes Yes Yes Yes
4 / 04 Currently in Use	4539	5/3/1971 35 / No	Diesel 6,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Galvanized Steel Impressed Current	Safe Suction	<div> <div>A B ● D E F G H I J K L</div> <div>● ● E F G H I J K L</div> </div>	Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed



## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** Town Pump Inc PO Box 6000 Butte MT 59701 Phone: (406) 497-6700

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5600767	Town Pump Inc Billings 1	1028 US Highway 87 E	Billings	59101	

TankID/Alt TankID	Tag Numbe	Installed	Product	Tank Mat'l of Construction	Piping Material	Piping Type	Tank Release Detection	FR Met																								
Status		Age/AST	Capacity	Secondary Option	Secondary Option		Piping Release Detection	Spill/Overl/C																								
6 / 06 Currently in Use	4583	10/2/1996 09 / No	Gasoline 12,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td>B</td><td></td><td></td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L	B			<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L																					
B			<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L																					
7 / 07 Currently in Use	2665	10/2/1996 09 / No	Gasoline 12,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td>B</td><td></td><td></td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L	B			<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L																					
B			<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L																					
8 / 08 Currently in Use	2666	10/2/1996 09 / No	Gasoline 12,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td>B</td><td></td><td></td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L	B			<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L																					
B			<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L																					
9 / 09 Currently in Use	2667	10/2/1996 09 / No	Diesel 12,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td>B</td><td></td><td></td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L	B			<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L																					
B			<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L																					
10 / 10 Currently In Use	3921	2/1/1999 07 / No	Diesel 6,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td>B</td><td></td><td></td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L	B			<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L																					
B			<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L																					

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** Western Sugar Co 7555 E Hampden Ave Ste 600 Denver CO 80231 Phone: (303) 813-3519

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5600773	Western Sugar Co	3020 State Ave	Billings	59101	(406) 245-6393

TankID/Alt TankID	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection	Piping Release Detection	FR Met
4 / S4	4969	7/1/1969	Other	Concrete	Bare Steel	Safe Suction	A B C D E F G H I J K L		Yes
Temporarily Out of Use		37 / Ye	435,120	None	None		B D E F G H I J K L		Yes Yes No

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** Montana State University Billings 1500 University Dr Billings MT 59101 Phone: (406) 657-2309

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5600904	MSU Facility Services Bldg	1500 University Dr	Billings	59101	(406) 657-2309

TankID/Alt TankID	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection	Piping Release Detection	FR Met
5 / 05 Currently in Use	846	9/1/1996 09 / No	Gasoline 1,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	U.S. Suction	<div> <div>A B C <input checked="" type="radio"/> E F <input checked="" type="radio"/> H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div>	<div> <div>A B C <input checked="" type="radio"/> E F <input checked="" type="radio"/> H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div>	Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** City of Billings Purchasing 1901 Terminal Circle RM216 PO Box 1178 Billings MT 59103 Phone: (406) 657-8495

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5600909	Billings Logan International Airport UST	1901 Terminal Cir Ste 216	Billings	59105	(406) 657-8491

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
2 / 11 Currently In Use	623	1/1/1987 19 / No	Diesel 4,000	STI-P3 Double-Walled	Fiberglass Reinforced Plastic Double-Walled	Pressurized	<div> <div>A B C D E F <input checked="" type="radio"/> H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div>	Yes Yes Yes Yes
3 / 12 Currently In Use	624	10/1/1993 12 / No	Gasoline 10,000	STI-P3 Double-Walled	Fiberglass Reinforced Plastic Double-Walled	Pressurized	<div> <div>A B C D E F <input checked="" type="radio"/> H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div>	Yes Yes Yes Yes
4 / 13 Currently In Use	625	10/1/1993 12 / No	Diesel 10,000	STI-P3 Double-Walled	Fiberglass Reinforced Plastic Double-Walled	Pressurized	<div> <div>A B C D E F <input checked="" type="radio"/> H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div>	Yes Yes Yes Yes
17 / 17 Currently In Use	4826	10/1/1993 12 / No	Used Oil 500	STI-P3 Double-Walled	Fiberglass Reinforced Plastic Double-Walled/Non-Corro	Gravity Feed	<div> <div>A B C D E F <input checked="" type="radio"/> H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div>	Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** Northwestern Corp 40 E Broadway St Butte MT 59701 Phone: (406) 497-3000

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5601188	Billings Service Center	405 S 20th St W	Billings	59102	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
1 / 04 Currently in Use		/ No	Other 300	Concrete None	Fiberglass Reinforced Plastic None	Not Listed	<div> <div>A B C D E F G H I J K L</div> <div>B D E F G H I J K L</div> </div>	Yes Yes Yes Yes
2 / 05 Currently in Use		/ No	Other 500	Concrete None	Fiberglass Reinforced Plastic None	Not Listed	<div> <div>A B C D E F G H I J K L</div> <div>B D E F G H I J K L</div> </div>	Yes Yes Yes Yes
3 / 3-1 Currently in Use	1683	4/30/1980 26 / No	Gasoline 4,000	Cathodically Protected Steel None	Bare Steel Impressed Current	Pressurized	<div> <div>A B C D E F G H I J K L</div> <div>D E F G H I J K L</div> </div>	Yes Yes Yes Yes
4 / 3-2 Currently in Use	1684	4/30/1980 26 / No	Diesel 2,000	Cathodically Protected Steel None	Bare Steel Impressed Current	Safe Suction	<div> <div>A B C D E F G H I J K L</div> <div>B D E F G H I J K L</div> </div>	Yes Yes Yes Yes
5 / 3-3 Currently in Use	1685	4/30/1980 26 / No	Gasoline 4,000	Cathodically Protected Steel None	Bare Steel Impressed Current	Safe Suction	<div> <div>A B C D E F G H I J K L</div> <div>B D E F G H I J K L</div> </div>	Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** W G Properties LLC PO Box 80391 Billings MT 59108 Phone: (406) 651-5101

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5601290	GM Petroleum Dist Inc Cardtrol Site 3	1004 4th Ave N	Billings	59101	(406) 252-4661

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
1 / D-1 Currently in Use	752	2/4/1976 30 / No	Diesel 20,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic Double-Walled	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B <input checked="" type="radio"/> D E F <input checked="" type="radio"/> H I J K L</div> </div>	Yes Yes Yes Yes
2 / D-2 Currently in Use	753	1/1/1976 30 / No	Diesel 20,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic Double-Walled	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B <input checked="" type="radio"/> <input checked="" type="radio"/> E F <input checked="" type="radio"/> H I J K L</div> </div>	Yes Yes Yes Yes
3 / D-3 Currently in Use	754	2/4/1976 30 / No	Diesel 20,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic Double-Walled	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B <input checked="" type="radio"/> <input checked="" type="radio"/> E F <input checked="" type="radio"/> H I J K L</div> </div>	Yes Yes Yes Yes
4 / D-4 Currently in Use	755	2/4/1976 30 / No	Diesel 20,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B <input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
5 / D-5 Currently in Use	756	2/4/1976 30 / No	Gasoline 20,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic Double-Walled	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B <input checked="" type="radio"/> D E F <input checked="" type="radio"/> H I J K L</div> </div>	Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** USF Reddaway 833 Mallowney Ln Billings MT 59101 Phone: (406) 252-3877

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5601340	USF Reddaway UST	833 Mallowney Ln	Billings	59101	(406) 252-3877

TankID/Alt TankID	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection	Piping Release Detection	FR Met
3 / 03 Currently in Use	3154	8/1/1993 12 / No	Diesel 10,000	STI-P3 None	Fiberglass Reinforced Plastic None	Safe Suction	<div> <div>A</div> <div><input checked="" type="radio"/></div> <div>D</div> <div>E</div> <div>F</div> <div>G</div> <div>H</div> <div>I</div> <div>J</div> <div>K</div> <div>L</div> </div>	<div> <div>B</div> <div>D</div> <div>E</div> <div>F</div> <div>G</div> <div>H</div> <div>I</div> <div><input checked="" type="radio"/></div> <div>K</div> <div>L</div> </div>	<div>Yes</div> <div>Yes Yes Yes</div>

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** Cenex Petroleum Inc PO Box 64089 MS 535 Saint Paul MN 55164 Phone: (651) 355-5583

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5601664	Kum and Go Store 826	16 Shiloh Road	Billings	59106	(406) 652-6874

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
1 / 01 Currently In Use	4344	12/31/1984 21 / No	Gasoline 12,000	Asphalt Coated or Bare Steel Impressed Current	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F <input checked="" type="radio"/> H I J K L</div> </div>	Yes Yes Yes Yes
2 / 02 Currently In Use	4345	12/31/1984 21 / No	Gasoline 12,000	Asphalt Coated or Bare Steel Impressed Current	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F <input checked="" type="radio"/> H I J K L</div> </div>	Yes Yes Yes Yes
3 / 03 Currently in Use	4346	11/10/1989 16 / No	Gasoline 10,000	STI-P3 Impressed Current	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F <input checked="" type="radio"/> H I J K L</div> </div>	Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed



## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** Cenex Petroleum Inc PO Box 64089 MS 535 Saint Paul MN 55164 Phone: (651) 355-5583

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5601665	Kum and Go Store 827	1046 N 27th St	Billings	59101	(406) 252-9654

TankID/Alt TankID	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction	Piping Material		Tank Release Detection	FR Met																								
Status				Secondary Option	Secondary Option	Piping Type	Piping Release Detection	Spill/Overl/C																								
3 / 03 Currently In Use	3080	1/28/1998 08 / No	Gasoline 15,000	Fiberglass Reinforced Plastic Double-Walled	Fiberglass Reinforced Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td></td><td>B</td><td></td><td>D</td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L		B		D	E	F	<input checked="" type="radio"/>	H	I	J	K	L	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					
	B		D	E	F	<input checked="" type="radio"/>	H	I	J	K	L																					
4 / 04 Currently In Use	3081	1/28/1998 08 / No	Gasoline 12,000	Fiberglass Reinforced Plastic Double-Walled	Fiberglass Reinforced Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td></td><td>B</td><td></td><td>D</td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L		B		D	E	F	<input checked="" type="radio"/>	H	I	J	K	L	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					
	B		D	E	F	<input checked="" type="radio"/>	H	I	J	K	L																					

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** MT State Womens Prison 701 South 27th St Billings MT 59101 Phone: (406) 247-5100

<b>Sys Fac I</b>	<b>Location Name</b>	<b>Location Street Address</b>	<b>Location City</b>	<b>Zip</b>	<b>Location Phone</b>
5601757	MT State Womens Prison	701 S 27th St	Billings	59101	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
2 / 02 Currently in Use	5053	10/1/2005 00 / No	Diesel 2,000	STI-P3 Double-Walled	Flexible Plastic Double-Walled	Safe Suction	<div style="display: flex; justify-content: space-between; padding: 2px;"> <span>(A) (B) (C) (D) (E) (F) (G) (H) (I) (J) (K) (L)</span> </div> <div style="display: flex; justify-content: space-between; padding: 2px;"> <span>(B) (D) (E) (F) (G) (H) (I) (J) (K) (L)</span> </div>	Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** Deaconess Billings Clinic 2800 10th Ave N Billings MT 59101 Phone: (406) 657-4030

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5602067	Deaconess Billings Clinic 9th Ave	2813 9th Ave N	Billings	59101	(406) 657-4030

TankID/Alt TankID	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection	Piping Release Detection	FR Met
2 / 02 Currently in Use	826	2/1/1992 14 / No	Diesel 10,000	Cathodically Protected Steel Double-Walled	Bare Steel Double-Walled/Non-Corro	U.S. Suction	<div> <div>A B C <input checked="" type="radio"/> E F <input checked="" type="radio"/> H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I <input checked="" type="radio"/> K L</div> </div>	<div> <div>A B C <input checked="" type="radio"/> E F <input checked="" type="radio"/> H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I <input checked="" type="radio"/> K L</div> </div>	Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** Federal Aviation Admin 1540 Lake Elmo Dr Ste 6 Billings MT 59105 Phone: (406) 657-6981

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5602551	Federal Aviation Admin Billings ASR 7	AMT Highway 7	Billings	59105	(406) 245-9928

TankID/Alt TankID	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection	Piping Release Detection	FR Met
2 / 02 Currently In Use	1050	8/1/1997 08 / No	Diesel 1,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	U.S. Suction	<div> <div>A</div> <div><input checked="" type="radio"/></div> <div>B</div> <div>C</div> <div>D</div> <div>E</div> <div>F</div> <div><input checked="" type="radio"/></div> <div>H</div> <div>I</div> <div>J</div> <div>K</div> <div>L</div> </div>	<div> <div>B</div> <div>D</div> <div>E</div> <div>F</div> <div><input checked="" type="radio"/></div> <div>H</div> <div>I</div> <div>J</div> <div>K</div> <div>L</div> </div>	No Yes Yes Yes

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** Saint Vincent Hospital & Health Center  
 PO Box 35200 Billings MT 59107 Phone: (406) 237-3065

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5602666	Saint Vincent Hospital & Health Center	1233 N 30th St	Billings	59101	(406) 657-7000

TankID/Alt TankID	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction	Piping Material	Piping Type	Tank Release Detection	FR Met																								
Status				Secondary Option	Secondary Option		Piping Release Detection	Spill/Overl/C																								
5 / S5 Currently In Use	1953	11/8/1999 06 / Ye	Diesel 4,000	Asphalt Coated or Bare Steel None	Copper Double-Walled/Non-Corro	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td><input checked="" type="radio"/></td><td>L</td></tr><tr><td colspan="2">B</td><td>D</td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td><td></td></tr></table>	A	B	C	D	E	F	G	H	I	J	<input checked="" type="radio"/>	L	B		D	E	F	<input checked="" type="radio"/>	H	I	J	K	L		Yes Yes Yes Yes
A	B	C	D	E	F	G	H	I	J	<input checked="" type="radio"/>	L																					
B		D	E	F	<input checked="" type="radio"/>	H	I	J	K	L																						
6 / S6 Currently In Use	1954	11/8/1999 06 / Ye	Diesel 4,000	Asphalt Coated or Bare Steel None	Copper Double-Walled/Non-Corro	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td><input checked="" type="radio"/></td><td>L</td></tr><tr><td colspan="2">B</td><td>D</td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td><td></td></tr></table>	A	B	C	D	E	F	G	H	I	J	<input checked="" type="radio"/>	L	B		D	E	F	<input checked="" type="radio"/>	H	I	J	K	L		Yes Yes Yes Yes
A	B	C	D	E	F	G	H	I	J	<input checked="" type="radio"/>	L																					
B		D	E	F	<input checked="" type="radio"/>	H	I	J	K	L																						

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** Associated Food Stores Inc Billings PO Box 2513 Billings MT 59103 Phone: (406) 245-3177

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5602823	Associated Food Stores Inc Billings	332 S Plainview St	Billings	59101	(406) 245-3177

TankID/Alt TankID	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection	Piping Release Detection	FR Met
4 / 04 Currently In Use	394	9/1/1998 07 / No	Diesel 12,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Safe Suction	<div> <div>A B C <input checked="" type="radio"/> E F <input checked="" type="radio"/> H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I <input checked="" type="radio"/> K L</div> </div>	<div> <div>A B C <input checked="" type="radio"/> E F <input checked="" type="radio"/> H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I <input checked="" type="radio"/> K L</div> </div>	Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** Greyhound Lines Inc 2502 1st Ave N MS 0084 Billings MT 59101 Phone: (214) 849-8842

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5603095	Greyhound Lines Inc	2502 1st Ave N	Billings	59101	(406) 252-8259

TankID/Alt TankID	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C																										
2 / 02 Currently In Use	1243	10/1/1997 08 / No	Diesel 15,000	Composite (Steel w/ FRP) Double-Walled	Flexible Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td colspan="3">B</td><td colspan="3">D</td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	B			D			E	F	<input checked="" type="radio"/>	H	I	J	K	L	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																							
B			D			E	F	<input checked="" type="radio"/>	H	I	J	K	L																					

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** 17 Poly LLC 1704 Poly Dr Billings MT 59102 Phone: (406) 245-6944

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5603522	17th Street Conoco	1701 Poly Dr	Billings	59102	(406) 245-6944

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
2 / 05 Currently in Use	4721	1/17/1989 17 / No	Gasoline 6,000	STI-P3 None	Bare Steel Cathodically Protected	Safe Suction	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F G H I <input checked="" type="radio"/> K L</div> </div>	Yes Yes Yes Yes
4 / 07 Currently in Use	4722	1/17/1989 17 / No	Gasoline 6,000	STI-P3 None	Bare Steel Cathodically Protected	Safe Suction	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F G H I <input checked="" type="radio"/> K L</div> </div>	Yes Yes Yes Yes
5 / 06 Currently in Use	4723	1/17/1989 17 / No	Gasoline 6,000	STI-P3 None	Bare Steel Cathodically Protected	Safe Suction	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F G H I <input checked="" type="radio"/> K L</div> </div>	Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed



## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** Edwards Jet Center 1691 Aviation PI Billings MT 59105 Phone: (406) 252-0508

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5603656	West End Logan International Airport	MT Highway 3	Billings	59105	(406) 247-3193

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
1 / 02 Currently in Use	764	5/1/1978 28 / No	Gasoline 12,000	Cathodically Protected Steel Lined Interior/Impressed Curr	No Piping None	Safe Suction	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F G H I J K L</div> </div>	Yes Yes Yes Yes
2 / 03 Currently in Use	765	5/1/1978 28 / No	Kerosene 12,000	Asphalt Coated or Bare Steel Impressed Current	No Piping None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F G H I J K L</div> </div>	Yes Yes Yes Yes
3 / 04 Currently in Use	766	5/1/1978 28 / No	Kerosene 12,000	Asphalt Coated or Bare Steel Impressed Current	No Piping None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F G H I J K L</div> </div>	Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** Yellowstone County Public Works      PO Box 35024   Billings   MT   59107   Phone: (406) 256-2735  
Dept

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5603658	Yellowstone County Public Works Dept	3321 King Ave E	Billings	59101	(406) 256-6812

TankID/Alt TankID	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
6 / 06 Currently In Use	4092	6/1/1999 07 / No	Used Oil 2,000	STI-P3 Double-Walled	Flexible Plastic Double-Walled	Safe Suction	<div> <div> A B C <input checked="" type="radio"/> E F <input checked="" type="radio"/> H I J K L </div> <div> B D E F <input checked="" type="radio"/> H I <input checked="" type="radio"/> K L </div> </div>	Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** Intermountain Distributing Inc 3927 1st Ave S Billings MT 59101 Phone: (406) 245-7744

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5603974	Intermountain Distributing Inc	3927 1st Ave S	Billings	59101	(406) 245-7744

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
1 / 05 Currently in Use	1410	1/1/1994 12 / No	Diesel 6,000	Fiberglass Reinforced Plastic Double-Walled	Fiberglass Reinforced Plastic None	Safe Suction	<div> <div>A B C D E F G H I J K L</div> <div>B D E F G H I J K L</div> </div>	Yes Yes Yes Yes
3 / 04 Currently in Use	1409	1/1/1994 12 / No	Gasoline 5,000	Fiberglass Reinforced Plastic Double-Walled	Fiberglass Reinforced Plastic None	Safe Suction	<div> <div>A B C D E F G H I J K L</div> <div>B D E F G H I J K L</div> </div>	Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** Sysco Food Services of Montana PO Box 31198 Billings MT 59107 Phone: (406) 247-1131

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5604077	Motor Pool	302 Edward St	Billings	59102	(406) 657-8216

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
3 / 03 Temporarily Out of Use	626	1/1/1988 18 / No	Gasoline 10,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
6 / 06 Temporarily Out of Use	627	10/4/1993 12 / No	Gasoline 5,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
7 / 07 Temporarily Out of Use	628	10/4/1993 12 / No	Diesel 5,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
8 / 08 Temporarily Out of Use	629	9/22/1993 12 / No	Diesel 10,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** Big Sky Linen Supply 715 Central Ave Billings MT 59102 Phone: (406) 252-5172

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5604214	Big Sky Linen Supply	715 Central Ave	Billings	59102	(406) 252-5172

TankID/Alt TankID	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection	Piping Release Detection	FR Met
2 / 02 Currently In Use	445	4/1/1998 08 / No	Gasoline 1,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Safe Suction	<div> <div>A</div> <div><input checked="" type="radio"/></div> <div>D</div> <div>E</div> <div>F</div> <div>G</div> <div>H</div> <div>I</div> <div>J</div> <div>K</div> <div>L</div> </div>	<div> <div>B</div> <div>D</div> <div>E</div> <div>F</div> <div>G</div> <div>H</div> <div>I</div> <div><input checked="" type="radio"/></div> <div>K</div> <div>L</div> </div>	Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** 17 Poly LLC 1704 Poly Dr Billings MT 59102 Phone: (406) 245-6944

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5604414	Poly Conoco	1704 Poly Dr	Billings	59102	(406) 245-6944

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
5 / 05 Currently In Use	4718	2/11/1998 08 / No	Gasoline 10,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
6 / 06 Currently In Use	4719	2/11/1998 08 / No	Gasoline 7,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
7 / 07 Currently In Use	4720	2/11/1998 08 / No	Diesel 3,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** Meadow Gold Dairies Inc PO Box 929 Billings MT 59103 Phone: (406) 252-2118

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5604464	Meadow Gold Dairies Inc Billings	109 S 28th St	Billings	59101	(406) 252-2118

TankID/Alt TankID	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection	Piping Release Detection	FR Met
2 / 02 Currently in Use	4264	8/7/1989 16 / No	Diesel 10,000	STI-P3 None	Galvanized Steel Cathodically Protected	U.S. Suction	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> D E F G H I J K L</div> </div>	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> D E F G H I J K L</div> </div>	Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** First Group America Corp 705 Central Ave Ste 300 Cincinnati OH 45202 Phone:

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5604467	First Student Inc	425 Sugar Ave	Billings	59101	(406) 248-3667

TankID/Alt TankID	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection	Piping Release Detection	FR Met
4 / 04 Currently In Use	1869	7/25/1997 08 / No	Diesel 12,000	Fiberglass Reinforced Plastic Double-Walled	Fiberglass Reinforced Plastic Double-Walled	Safe Suction	<div> <div>A B C <input checked="" type="radio"/> E F <input checked="" type="radio"/> H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I <input checked="" type="radio"/> K L</div> </div>	<div> <div>A B C <input checked="" type="radio"/> E F <input checked="" type="radio"/> H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I <input checked="" type="radio"/> K L</div> </div>	Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed



## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** United Parcel Service 547 S 20th St W Ste 6 Billings MT 59102 Phone: (406) 656-8964

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5604542	United Parcel Service Billings	1830 Lampman Dr	Billings	59102	(406) 652-8772

TankID/Alt TankID	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction	Piping Material	Piping Type	Tank Release Detection	FR Met																								
Status				Secondary Option	Secondary Option		Piping Release Detection	Spill/Overl/C																								
5 / 05 Currently in Use	2183	7/20/1993 12 / No	Diesel 12,000	Fiberglass Reinforced Plastic Double-Walled	Fiberglass Reinforced Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td></td><td>B</td><td></td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L		B		<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L																					
	B		<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L																					
6 / 06 Currently in Use	2184	7/20/1993 12 / No	Gasoline 12,000	Fiberglass Reinforced Plastic Double-Walled	Fiberglass Reinforced Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td></td><td>B</td><td></td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L		B		<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L																					
	B		<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L																					

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** Bob Smith Lincoln Mercury PO Box 20838 Billings MT 59104 Phone: (406) 656-0000

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5604774	Bob Smith Lincoln Mercury	2244 Central Ave	Billings	59102	(406) 656-0000

TankID/Alt TankID	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection	Piping Release Detection	FR Met
1 / 03 Currently in Use	3585	12/20/1988 17 / No	Gasoline 1,000	STI-P3 None	Bare Steel Cathodically Protected	Safe Suction	<div> <input checked="" type="radio"/> B           <input type="radio"/> C           <input type="radio"/> D           <input type="radio"/> F           <input type="radio"/> G           <input type="radio"/> H           <input type="radio"/> I           <input type="radio"/> J           <input type="radio"/> K           <input type="radio"/> L         </div>	<div> <input type="radio"/> B           <input type="radio"/> D           <input type="radio"/> E           <input type="radio"/> F           <input type="radio"/> G           <input type="radio"/> H           <input type="radio"/> I           <input checked="" type="radio"/> J           <input type="radio"/> K           <input type="radio"/> L         </div>	Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** Stockton Oil Co 1607 4th Ave N PO Box 1756 Billings MT 59103 Phone: (406) 245-6376

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5604839	Stockton Oil Co 4th Ave N	1607 4th Ave N	Billings	59101	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
1 / 01 Currently in Use	1988	3/26/1980 26 / No	Diesel 6,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
5 / 06 Currently in Use	1989	4/1/1992 14 / No	Diesel 5,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
6 / 07 Currently in Use	1990	4/1/1992 14 / No	Diesel 8,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
7 / 08 Currently in Use	1991	4/1/1992 14 / No	Gasoline 8,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
8 / 09 Currently in Use	1992	4/1/1992 14 / No	Diesel 8,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
9 / 10 Currently in Use	1993	4/1/1992 14 / No	Gasoline 8,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
10 / 11 Currently in Use		7/1/1994 12 / No	Other 1,000	STI-P3 None	Fiberglass Reinforced Plastic None	Not Listed	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J <input checked="" type="radio"/> L</div> </div>	Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** SNG Inc 4410 State Ave Billings MT 59101 Phone: (406) 245-0161

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5604946	3 Gs Convenience Center State Ave	4410 State Ave	Billings	59101	(406) 256-6246

TankID/Alt TankID	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction	Piping Material	Piping Type	Tank Release Detection	FR Met																								
Status				Secondary Option	Secondary Option		Piping Release Detection	Spill/Overl/C																								
1 / 01 Currently in Use	4747	4/1/1985 21 / No	Gasoline 6,000	STI-P3 Lined Interior/Impressed Curr	Fiberglass Reinforced Plastic Cathodically Protected	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>●</td><td>J</td><td>K</td><td>L</td></tr><tr><td>●</td><td></td><td></td><td>●</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	D	E	F	G	H	●	J	K	L	●			●	E	F	G	H	I	J	K	L	Yes Yes Yes Yes
A	B	C	D	E	F	G	H	●	J	K	L																					
●			●	E	F	G	H	I	J	K	L																					
2 / 02 Currently in Use	4748	4/1/1985 21 / No	Gasoline 10,000	STI-P3 Lined Interior/Impressed Curr	Fiberglass Reinforced Plastic None	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>●</td><td>J</td><td>K</td><td>L</td></tr><tr><td>●</td><td></td><td></td><td>●</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	D	E	F	G	H	●	J	K	L	●			●	E	F	G	H	I	J	K	L	Yes Yes Yes Yes
A	B	C	D	E	F	G	H	●	J	K	L																					
●			●	E	F	G	H	I	J	K	L																					

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** Stockton Oil Co 1607 4th Ave N PO Box 1756 Billings MT 59103 Phone: (406) 245-6376

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5604950	State Ave Drug & Hardware	4188 State Ave	Billings	59101	(406) 245-0072

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
1 / 01 Currently in Use	3778	3/26/1985 21 / No	Gasoline 6,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Galvanized Steel Impressed Current	Pressurized	<div> <div>A B ● D E F G H I J K L</div> <div>B ● E F G H I J K L</div> </div>	Yes Yes Yes Yes
2 / 02 Currently in Use	3779	3/26/1985 21 / No	Gasoline 6,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Galvanized Steel Impressed Current	Pressurized	<div> <div>A B ● D E F G H I J K L</div> <div>B ● E F G H I J K L</div> </div>	Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** Stockton Oil Co 1607 4th Ave N PO Box 1756 Billings MT 59103 Phone: (406) 245-6376

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5604951	SOCO Express 10	5400 Laurel Road	Billings	59101	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
5 / 05 Currently in Use	1994	5/1/1991 15 / No	Gasoline 8,000	Cathodically Protected Steel None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
6 / 06 Currently in Use	1995	5/1/1991 15 / No	Gasoline 8,000	Cathodically Protected Steel None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
7 / 07 Currently in Use	1996	5/1/1991 15 / No	Gasoline 8,000	Cathodically Protected Steel None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
8 / 08 Currently in Use	1997	5/1/1991 15 / No	Diesel 8,000	Cathodically Protected Steel None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
9 / 09 Currently in Use	1998	5/1/1991 15 / No	Diesel 15,000	Cathodically Protected Steel None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** Jim McCombs 1303 Central Ave Billings MT 59102 Phone: (406) 252-0350

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5604953	J & S Pioneer Service	1303 Central Ave	Billings	59102	(406) 252-0350

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
1 / 01 Currently in Use	1999	3/26/1985 21 / No	Gasoline 8,000	STI-P3 None	Galvanized Steel Cathodically Protected	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
2 / 02 Currently in Use	2000	3/26/1985 21 / No	Gasoline 8,000	STI-P3 None	Galvanized Steel Cathodically Protected	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
4 / 04 Currently in Use	2001	5/3/1991 15 / No	Gasoline 2,000	STI-P3 None	Galvanized Steel Cathodically Protected	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** SNG Inc 4410 State Ave Billings MT 59101 Phone: (406) 245-0161

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5604954	Kwik Way 21	1503 Grand Ave	Billings	59102	(406) 256-0386

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
3 / 04 Currently in Use	3780	6/1/1988 18 / No	Gasoline 10,000	STI-P3 None	Galvanized Steel Cathodically Protected	Pressurized	<div> <div>A B C D E F G H J K L</div> <div> <input checked="" type="radio"/> <input type="radio"/> E F G H I J K L </div> </div>	Yes Yes Yes Yes
4 / 05 Currently in Use	3781	3/26/1986 20 / No	Gasoline 10,000	STI-P3 None	Galvanized Steel Cathodically Protected	Pressurized	<div> <div>A B C D E F G H J K L</div> <div> <input type="radio"/> <input checked="" type="radio"/> E F G H I J K L </div> </div>	Yes Yes Yes Yes
5 / 06 Currently in Use	3782	3/26/1986 20 / No	Gasoline 10,000	STI-P3 None	Galvanized Steel Cathodically Protected	Pressurized	<div> <div>A B C D E F G H J K L</div> <div> <input type="radio"/> <input checked="" type="radio"/> E F G H I J K L </div> </div>	Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed



## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** Stockton Oil Co 1607 4th Ave N PO Box 1756 Billings MT 59103 Phone: (406) 245-6376

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5604955	South 27th Express Center	1239 S 27th St	Billings	59101	(406) 259-0680

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
1 / 03 Currently in Use	3785	3/26/1977 29 / No	Gasoline 8,000	Asphalt Coated or Bare Steel Impressed Current	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C D E F G H J K L</div> <div>B ● E F G H ● J K L</div> </div>	Yes Yes Yes Yes
2 / 01 Currently in Use	3783	3/26/1969 37 / No	Gasoline 8,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C D E F G H J K L</div> <div>B ● E F G H ● J K L</div> </div>	Yes Yes Yes Yes
3 / 02 Currently in Use	3784	3/26/1969 37 / No	Gasoline 8,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C D E F G H J K L</div> <div>B ● E F G H ● J K L</div> </div>	Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** Stockton Oil Co 1607 4th Ave N PO Box 1756 Billings MT 59103 Phone: (406) 245-6376

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5604956	Kwik Way 7	1503 Broadwater Ave	Billings	59102	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
1 / 01 Currently in Use	3751	3/26/1977 29 / No	Gasoline 8,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C D E F G H J K L</div> <div> <input checked="" type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> </div> </div>	No Yes Yes Yes
2 / 02 Currently in Use	3752	3/26/1969 37 / No	Gasoline 8,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C D E F G H J K L</div> <div> <input checked="" type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> </div> </div>	No Yes Yes Yes
3 / 03 Currently in Use	3753	3/26/1969 37 / No	Gasoline 8,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C D E F G H J K L</div> <div> <input checked="" type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> </div> </div>	No Yes Yes Yes

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** SNG Inc 4410 State Ave Billings MT 59101 Phone: (406) 245-0161

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5604957	3 Gs Convenience Center E Wicks Lane	1221 Wicks Ln	Billings	59105	(406) 245-4539

TankID/Alt TankID	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction	Piping Material		Tank Release Detection	FR Met																									
Status				Secondary Option	Secondary Option	Piping Type	Piping Release Detection	Spill/Overl/C																									
1 / 01 Currently in Use	4749	3/26/1985 21 / No	Gasoline 10,000	STI-P3 None	Galvanized Steel Cathodically Protected	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>●</td><td>J</td><td>K</td><td>L</td></tr><tr><td>B</td><td></td><td></td><td></td><td>●</td><td>E</td><td>F</td><td>G</td><td>H</td><td>●</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	D	E	F	G	H	●	J	K	L	B				●	E	F	G	H	●	J	K	L	No Yes Yes Yes
A	B	C	D	E	F	G	H	●	J	K	L																						
B				●	E	F	G	H	●	J	K	L																					
2 / 02 Currently in Use	4750	3/26/1985 21 / No	Gasoline 10,000	STI-P3 None	Galvanized Steel Cathodically Protected	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>●</td><td>J</td><td>K</td><td>L</td></tr><tr><td>B</td><td></td><td></td><td></td><td>●</td><td>E</td><td>F</td><td>G</td><td>H</td><td>●</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	D	E	F	G	H	●	J	K	L	B				●	E	F	G	H	●	J	K	L	No Yes Yes Yes
A	B	C	D	E	F	G	H	●	J	K	L																						
B				●	E	F	G	H	●	J	K	L																					

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** Pacific Coast Building Products PO Box 160488 Sacramento CA 95816 Phone: (916) 444-9304

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5604965	Pacific Supply	600 Daniel St	Billings	59101	(406) 254-8876

TankID/Alt TankID	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection	Piping Release Detection	FR Met
3 / 03 Currently in Use	4350	11/1/1993 12 / No	Diesel 10,000	Fiberglass Reinforced Plastic Double-Walled	Bare Steel Double-Walled/Non-Corro	Safe Suction	<div> <div>A B C D E F G H I J K L</div> <div>B D E F G H I J K L</div> </div>	<div> <div>A B C D E F G H I J K L</div> <div>B D E F G H I J K L</div> </div>	Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** Stockton Oil Co 1607 4th Ave N PO Box 1756 Billings MT 59103 Phone: (406) 245-6376

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5605072	Exxon RAS 6 3590	2344 Central Ave	Billings	59102	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
5 / 05 Currently in Use	2002	11/8/1994 11 / No	Gasoline 20,000	Cathodically Protected Steel None	Fiberglass Reinforced Plastic Double-Walled	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D <input checked="" type="radio"/> F G H I J K L</div> </div>	Yes Yes Yes Yes
6 / 06 Currently in Use	2003	11/8/1994 11 / No	Gasoline 10,000	Cathodically Protected Steel None	Fiberglass Reinforced Plastic Double-Walled	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D <input checked="" type="radio"/> F G H I J K L</div> </div>	Yes Yes Yes Yes
7 / 07 Currently in Use	2004	11/8/1994 11 / No	Gasoline 10,000	Cathodically Protected Steel None	Fiberglass Reinforced Plastic Double-Walled	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D <input checked="" type="radio"/> F G H I J K L</div> </div>	Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** Stockton Oil Co 1607 4th Ave N PO Box 1756 Billings MT 59103 Phone: (406) 245-6376

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5605074	Lockwood Interstate Exxon	1031 US Highway 87 E	Billings	59101	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
1 / 10 Temporarily Out of Use	2006	11/1/1993 12 / No	Diesel 6,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	No Yes Yes Yes
2 / 09 Currently in Use	2005	11/1/1993 12 / No	Diesel 8,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	No Yes Yes Yes
7 / 03 Currently in Use	3677	11/30/1987 18 / No	Gasoline 8,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	No Yes Yes Yes
9 / 02 Currently in Use	3676	11/30/1987 18 / No	Gasoline 10,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	No Yes Yes Yes
10 / 01 Currently in Use	3675	11/30/1987 18 / No	Gasoline 10,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	No Yes Yes Yes

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** Stockton Oil Co 1607 4th Ave N PO Box 1756 Billings MT 59103 Phone: (406) 245-6376

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5605075	Exxon RAS 6 3535	822 N 27th St	Billings	59101	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
5 / 05 Currently in Use	3678	8/1/1991 14 / No	Gasoline 8,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<div> <input type="radio"/>A<input checked="" type="radio"/>B<input type="radio"/>C<input checked="" type="radio"/>D<input type="radio"/>E<input type="radio"/>F<input type="radio"/>G<input type="radio"/>H<input type="radio"/>I<input type="radio"/>J<input type="radio"/>K<input type="radio"/>L                 </div> <div> <input checked="" type="radio"/>A<input type="radio"/>B<input checked="" type="radio"/>D<input type="radio"/>E<input type="radio"/>F<input type="radio"/>G<input type="radio"/>H<input type="radio"/>I<input type="radio"/>J<input type="radio"/>K<input type="radio"/>L                 </div>	No Yes Yes Yes
6 / 06 Currently in Use	3679	8/1/1991 14 / No	Gasoline 8,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<div> <input type="radio"/>A<input checked="" type="radio"/>B<input type="radio"/>C<input checked="" type="radio"/>D<input type="radio"/>E<input type="radio"/>F<input type="radio"/>G<input type="radio"/>H<input type="radio"/>I<input type="radio"/>J<input type="radio"/>K<input type="radio"/>L                 </div> <div> <input checked="" type="radio"/>A<input type="radio"/>B<input checked="" type="radio"/>D<input type="radio"/>E<input type="radio"/>F<input type="radio"/>G<input type="radio"/>H<input type="radio"/>I<input type="radio"/>J<input type="radio"/>K<input type="radio"/>L                 </div>	No Yes Yes Yes
7 / 07 Currently in Use	3680	8/1/1991 14 / No	Gasoline 8,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<div> <input type="radio"/>A<input checked="" type="radio"/>B<input type="radio"/>C<input checked="" type="radio"/>D<input type="radio"/>E<input type="radio"/>F<input type="radio"/>G<input type="radio"/>H<input type="radio"/>I<input type="radio"/>J<input type="radio"/>K<input type="radio"/>L                 </div> <div> <input checked="" type="radio"/>A<input type="radio"/>B<input checked="" type="radio"/>D<input type="radio"/>E<input type="radio"/>F<input type="radio"/>G<input type="radio"/>H<input type="radio"/>I<input type="radio"/>J<input type="radio"/>K<input type="radio"/>L                 </div>	No Yes Yes Yes

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** Joey Kellog Dennis Hust 1240 Avenue C Billings MT 59102 Phone: (406) 259-6922

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5605077	Exxon RAS 6 3494	1240 Avenue C	Billings	59102	(406) 259-6922

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
5 / 05 Currently in Use	3182	1/11/1994 12 / No	Gasoline 2,000	STI-P3 None	Fiberglass Reinforced Plastic Cathodically Protected	Safe Suction	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F G H I <input checked="" type="radio"/> K L</div> </div>	Yes Yes Yes Yes
6 / 06 Currently in Use	3183	1/11/1994 12 / No	Gasoline 4,000	STI-P3 None	Fiberglass Reinforced Plastic Cathodically Protected	Safe Suction	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F G H I <input checked="" type="radio"/> K L</div> </div>	Yes Yes Yes Yes
7 / 07 Currently in Use	3184	1/11/1994 12 / No	Gasoline 6,000	STI-P3 None	Fiberglass Reinforced Plastic Cathodically Protected	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed



## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** Stockton Oil Co 1607 4th Ave N PO Box 1756 Billings MT 59103 Phone: (406) 245-6376

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5605085	Kwik Way 14	3443 Central Ave	Billings	59102	(406) 652-9908

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
5 / 08 Currently in Use	2009	5/1/1995 11 / No	Gasoline 6,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C D E F G H J K L</div> <div> <input checked="" type="radio"/> <input type="radio"/> E F G H I J K L </div> </div>	Yes Yes Yes Yes
6 / 06 Currently in Use	2007	5/1/1995 11 / No	Gasoline 4,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C D E F G H J K L</div> <div> <input checked="" type="radio"/> <input type="radio"/> E F G H I J K L </div> </div>	Yes Yes Yes Yes
7 / 07 Currently in Use	4473	5/1/1995 11 / No	Gasoline 8,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C D E F G H J K L</div> <div> <input checked="" type="radio"/> <input type="radio"/> E F G H I J K L </div> </div>	Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** GM Petroleum Dist Inc PO Box 30335 Billings MT 59107 Phone: (406) 252-4661

<b>Sys Fac I</b>	<b>Location Name</b>	<b>Location Street Address</b>	<b>Location City</b>	<b>Zip</b>	<b>Location Phone</b>
5605086	Kwik Way 12	4040 Old Hardin Road	Billings	59101	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
1 / 01 Currently in Use	1151	4/25/1975 31 / No	Gasoline 10,000	Asphalt Coated or Bare Steel Impressed Current	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
2 / 02 Currently in Use	1152	4/25/1975 31 / No	Gasoline 4,000	Asphalt Coated or Bare Steel Impressed Current	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
3 / 03 Currently in Use	1153	4/25/1975 31 / No	Gasoline 4,000	Asphalt Coated or Bare Steel Impressed Current	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** Stockton Oil Co 1607 4th Ave N PO Box 1756 Billings MT 59103 Phone: (406) 245-6376

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5605087	Kwik Way 11	357 S 24th St W	Billings	59102	(406) 652-9904

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
1 / 05 Currently in Use	2012	3/1/1993 13 / No	Gasoline 8,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
2 / 04 Currently in Use	2011	3/1/1993 13 / No	Gasoline 8,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
3 / 03 Currently in Use	2010	3/1/1993 13 / No	Gasoline 8,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** Kwik Way Inc PO Box 20799 Billings MT 59104 Phone: (406) 656-6310

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5605088	Kwik Way 13	11 W Wicks Ln	Billings	59105	(406) 256-3831

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
1 / 05 Currently in Use	1156	11/16/1990 15 / No	Gasoline 6,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
2 / 03 Currently in Use	1154	11/16/1990 15 / No	Gasoline 10,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
3 / 04 Currently in Use	1155	11/16/1990 15 / No	Gasoline 8,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** Stockton Oil Co 1607 4th Ave N PO Box 1756 Billings MT 59103 Phone: (406) 245-6376

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5605090	Kwik Way 8	3306 Rimrock Road	Billings	59102	(406) 652-5560

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
1 / 01 Currently in Use	3681	11/30/1987 18 / No	Gasoline 10,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C D E F G H J K L</div> <div>B ● E F G H ● J K L</div> </div>	No Yes Yes Yes
2 / 02 Currently in Use	3682	11/30/1987 18 / No	Gasoline 10,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C D E F G H J K L</div> <div>B ● E F G H ● J K L</div> </div>	No Yes Yes Yes
3 / 03 Currently in Use	3683	11/30/1987 18 / No	Gasoline 8,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C D E F G H J K L</div> <div>B ● E F G H ● J K L</div> </div>	No Yes Yes Yes

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** Automatic Car Wash Inc 1133 Grand Ave Billings MT 59102 Phone: (406) 248-2558

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5605491	Dons Car Wash Grand Ave	1125 Grand Ave	Billings	59102	(406) 259-4955

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
2 / 04 Currently in Use	406	5/4/1988 18 / No	Gasoline 10,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
3 / 05 Currently in Use	407	5/4/1988 18 / No	Gasoline 10,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
4 / 06 Currently in Use	408	5/4/1988 18 / No	Gasoline 6,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** Automatic Car Wash Inc 1133 Grand Ave Billings MT 59102 Phone: (406) 248-2558

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5605492	Dons Car Wash Central Ave	2343 Central Ave	Billings	59102	(406) 656-7051

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
4 / 04 Currently in Use	409	5/1/1990 16 / No	Gasoline 10,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I <input checked="" type="radio"/> K L</div> </div>	Yes Yes Yes Yes
5 / 05 Currently in Use	4467	5/1/1990 16 / No	Gasoline 10,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I <input checked="" type="radio"/> K L</div> </div>	Yes Yes Yes Yes
6 / 06 Currently in Use	411	5/1/1990 16 / No	Diesel 6,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I <input checked="" type="radio"/> K L</div> </div>	Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** Kwik Way Inc PO Box 20799 Billings MT 59104 Phone: (406) 656-6310

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5605746	Kwik Way 19	2010 Henesta Dr	Billings	59102	(406) 652-9868

TankID/Alt TankID	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C																								
4 / 04 Currently In Use	3454	4/28/1998 08 / No	Gasoline 10,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					
<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					
5 / 05 Currently In Use	3455	4/28/1998 08 / No	Gasoline 10,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					
<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed



## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** Kwik Way Inc PO Box 20799 Billings MT 59104 Phone: (406) 656-6310

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5605748	Kwik Way 3	4106 State Ave	Billings	59101	(406) 259-0995

TankID/Alt TankID	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction	Piping Material		Tank Release Detection	FR Met																								
Status				Secondary Option	Secondary Option	Piping Type	Piping Release Detection	Spill/Overl/C																								
3 / 03 Currently In Use	4714	8/23/2002 03 / No	Gasoline 9,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td>B</td><td></td><td></td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	B			<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					
B			<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					
4 / 04 Currently In Use	4715	8/23/2002 03 / No	Gasoline 3,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td>B</td><td></td><td></td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	B			<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					
B			<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** Kwik Way Inc PO Box 20799 Billings MT 59104 Phone: (406) 656-6310

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5605749	Kwik Way 17	446 Grand Ave	Billings	59101	(406) 656-6310

TankID/Alt TankID	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction	Piping Material	Piping Type	Tank Release Detection	FR Met																								
Status				Secondary Option	Secondary Option		Piping Release Detection	Spill/Overl/C																								
5 / 05 Currently In Use	3456	11/1/1997 08 / No	Gasoline 10,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td>B</td><td></td><td></td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	B			<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					
B			<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					
6 / 06 Currently In Use	3457	11/1/1997 08 / No	Gasoline 10,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td>B</td><td></td><td></td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	B			<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					
B			<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** Quast Inc 1031 24th St W Billings MT 59102 Phone: (406) 652-1529

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5605750	24th Street Cenex	1031 24th St W	Billings	59102	(406) 652-1529

TankID/Alt TankID	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction	Piping Material		Tank Release Detection	FR Met																								
Status				Secondary Option	Secondary Option	Piping Type	Piping Release Detection	Spill/Overl/C																								
1 / 01 Currently in Use	3720	9/1/1984 21 / No	Gasoline 10,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td>B</td><td></td><td></td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	B			<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					
B			<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					
2 / 02 Currently in Use	3721	9/1/1984 21 / No	Gasoline 10,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td>B</td><td></td><td></td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	B			<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					
B			<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** Automatic Car Wash Inc 1133 Grand Ave Billings MT 59102 Phone: (406) 248-2558

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5605755	Dons Car Wash	1433 Main St	Billings	59105	(406) 256-1941

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
4 / 04 Currently In Use	5030	11/10/2005 00 / No	Gasoline 12,000	STI-P3 None	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B <input checked="" type="radio"/> E F <input checked="" type="radio"/> H I J K L</div> </div>	Yes Yes Yes Yes
5 / 05 Currently In Use	5031	11/10/2005 00 / No	Gasoline 6,000	STI-P3 None	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B <input checked="" type="radio"/> E F <input checked="" type="radio"/> H I J K L</div> </div>	Yes Yes Yes Yes
6 / 06 Currently In Use	5032	11/10/2005 00 / No	Diesel 6,000	STI-P3 None	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B <input checked="" type="radio"/> E F <input checked="" type="radio"/> H I J K L</div> </div>	Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** AT&T 900 Route 202 N Rm 5C106E Bedminster NJ 07921 Phone: (908) 234-7441

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5605758	AT & T Communications Billings	3011 2nd Ave N	Billings	59101	

TankID/Alt TankID	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection	Piping Release Detection	FR Met
Status									Spill/Overl/C
3 / 03 Currently in Use	399	9/1/1994 11 / No	Diesel 8,000	Composite (Steel w/ FRP) Double-Walled	Fiberglass Reinforced Plastic Double-Walled	U.S. Suction	<div> <div>A B C <input checked="" type="radio"/> E F <input checked="" type="radio"/> H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div>	<div> <div>A B C <input checked="" type="radio"/> E F <input checked="" type="radio"/> H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div>	Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** Interstate Brands Corp PO Box 81250 Billings MT 59108 Phone: (406) 248-4800

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5605997	Interstate Brands Corp Billings	5150 Midland Road	Billings	59101	(406) 248-4800

TankID/Alt TankID	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection	Piping Release Detection	FR Met
5 / S5 Currently in Use	1411	4/1/1993 13 / Ye	Heating Oil 18,000	Asphalt Coated or Bare Steel None	Fiberglass Reinforced Plastic Double-Walled	Pressurized	<div> <div>A B C D E F G H I J K L</div> <div>B D E F G H I J K L</div> </div>	<div> <div></div> <div></div> </div>	<div>Yes</div> <div>Yes Yes Yes</div>

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** Super Valu Inc 1629 King Ave W PO Box 30838 Billings MT 59107 Phone: (406) 247-1400

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5606097	Super Valu Inc Billings	1629 King Ave W	Billings	59102	(406) 247-1513

TankID/Alt TankID	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction	Piping Material	Piping Type	Tank Release Detection	FR Met																									
Status				Secondary Option	Secondary Option		Piping Release Detection	Spill/Overl/C																									
4 / 04 Currently In Use	1867	9/1/1998 07 / No	Diesel 12,000	STI-P3 Double-Walled	Flexible Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td></td><td>B</td><td></td><td></td><td>D</td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L		B			D	E	F	<input checked="" type="radio"/>	H	I	J	K	L	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																						
	B			D	E	F	<input checked="" type="radio"/>	H	I	J	K	L																					
5 / 05 Currently In Use	1868	9/1/1998 07 / No	Diesel 10,000	STI-P3 Double-Walled	Flexible Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td></td><td>B</td><td></td><td></td><td>D</td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L		B			D	E	F	<input checked="" type="radio"/>	H	I	J	K	L	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																						
	B			D	E	F	<input checked="" type="radio"/>	H	I	J	K	L																					

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** Food Services of America 802 Parkway Ln Billings MT 59101 Phone: (406) 238-7800

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5606132	Food Services of America Billings	802 Parkway Ln	Billings	59101	(406) 238-7800

TankID/Alt TankID	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection	Piping Release Detection	FR Met
2 / 05 Currently in Use	1781	11/2/1993 12 / No	Diesel 12,000	STI-P3 None	Bare Steel Cathodically Protected	Safe Suction	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F G H I <input checked="" type="radio"/> K L</div> </div>	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F G H I <input checked="" type="radio"/> K L</div> </div>	Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed



## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** GM Petroleum Dist Inc PO Box 30335 Billings MT 59107 Phone: (406) 252-4661

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5606137	Quality Concrete Co UST	2111 4th Ave N	Billings	59101	(406) 749-8022

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
3 / 03 Temporarily Out of Use	1157	7/30/1986 19 / No	Gasoline 1,000	STI-P3 None	Bare Steel Cathodically Protected	Safe Suction	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F G H I <input checked="" type="radio"/> K L</div> </div>	Yes Yes Yes Yes
4 / 04 Temporarily Out of Use	1158	7/30/1986 19 / No	Diesel 2,000	STI-P3 None	Bare Steel Cathodically Protected	Safe Suction	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F G H I <input checked="" type="radio"/> K L</div> </div>	Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** Blue Basket Markets 1004 Division St PO Box 531 Billings MT 59101 Phone: (406) 252-0166

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5606593	Blue Basket Food Market 2	2347 Main St	Billings	59105	(406) 252-7679

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
1 / 01 Currently in Use	459	10/1/1981 24 / No	Gasoline 6,000	Asphalt Coated or Bare Steel Impressed Current	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
2 / 02 Currently in Use	460	10/1/1981 24 / No	Gasoline 10,000	Asphalt Coated or Bare Steel Impressed Current	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
3 / 03 Currently in Use	461	10/1/1981 24 / No	Gasoline 10,000	Asphalt Coated or Bare Steel Impressed Current	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** Blue Basket Markets 1004 Division St PO Box 531 Billings MT 59101 Phone: (406) 252-0166

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5606594	Blue Basket Food Market 3	2816 Old Hardin Road	Billings	59101	(406) 248-6816

TankID/Alt TankID	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction	Piping Material	Piping Type	Tank Release Detection	FR Met																								
Status				Secondary Option	Secondary Option		Piping Release Detection	Spill/Overl/C																								
4 / 04 Currently In Use	462	5/1/1998 08 / No	Gasoline 20,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td colspan="2">B</td><td colspan="2">D</td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L	B		D		E	F	<input checked="" type="radio"/>	H	I	J	K	L	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L																					
B		D		E	F	<input checked="" type="radio"/>	H	I	J	K	L																					
5 / 05 Currently In Use	463	5/1/1998 08 / No	Gasoline 10,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td colspan="2">B</td><td colspan="2">D</td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L	B		D		E	F	<input checked="" type="radio"/>	H	I	J	K	L	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L																					
B		D		E	F	<input checked="" type="radio"/>	H	I	J	K	L																					
6 / 06 Currently In Use	464	5/1/1998 08 / No	Gasoline 8,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td colspan="2">B</td><td colspan="2">D</td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L	B		D		E	F	<input checked="" type="radio"/>	H	I	J	K	L	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L																					
B		D		E	F	<input checked="" type="radio"/>	H	I	J	K	L																					
7 / 07 Currently In Use	465	5/1/1998 08 / No	Diesel 8,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td colspan="2">B</td><td colspan="2">D</td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L	B		D		E	F	<input checked="" type="radio"/>	H	I	J	K	L	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L																					
B		D		E	F	<input checked="" type="radio"/>	H	I	J	K	L																					

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** Blue Basket Markets 1004 Division St PO Box 531 Billings MT 59101 Phone: (406) 252-0166

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5606595	Blue Basket Food Market 1	2007 Blue Creek Road	Billings	59101	(406) 248-4271

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
3 / 03 Currently in Use	466	11/2/1992 13 / No	Gasoline 6,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
4 / 04 Currently in Use	467	11/2/1992 13 / No	Gasoline 8,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
5 / 05 Currently in Use	468	11/2/1992 13 / No	Gasoline 8,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** Hoogies Truck Wash Inc PO Box 31494 Billings MT 59107 Phone: (406) 245-2887

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5606598	Hoogies Truck Wash Inc	2901 State Ave	Billings	59101	(406) 245-2887

TankID/Alt TankID	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction	Piping Material	Piping Type	Tank Release Detection	FR Met																								
Status				Secondary Option	Secondary Option		Piping Release Detection	Spill/Overl/C																								
1 / 01 Currently in Use	3768	4/1/1982 24 / No	Diesel 4,000	Asphalt Coated or Bare Steel Impressed Current	Galvanized Steel Impressed Current	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>●</td><td>J</td><td>K</td><td>L</td></tr><tr><td>●</td><td></td><td></td><td>●</td><td>E</td><td>F</td><td>G</td><td>H</td><td>●</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	D	E	F	G	H	●	J	K	L	●			●	E	F	G	H	●	J	K	L	Yes Yes Yes Yes
A	B	C	D	E	F	G	H	●	J	K	L																					
●			●	E	F	G	H	●	J	K	L																					
2 / 02 Currently in Use	3769	4/1/1982 24 / No	Diesel 10,000	Asphalt Coated or Bare Steel Impressed Current	Galvanized Steel Impressed Current	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>●</td><td>J</td><td>K</td><td>L</td></tr><tr><td>●</td><td></td><td></td><td>●</td><td>E</td><td>F</td><td>G</td><td>H</td><td>●</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	D	E	F	G	H	●	J	K	L	●			●	E	F	G	H	●	J	K	L	Yes Yes Yes Yes
A	B	C	D	E	F	G	H	●	J	K	L																					
●			●	E	F	G	H	●	J	K	L																					

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** Stockton Oil Co 1607 4th Ave N PO Box 1756 Billings MT 59103 Phone: (406) 245-6376

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5606609	Short Stop	804 Central Ave	Billings	59102	(406) 256-5032

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
1 / 01 Currently in Use	3754	3/26/1981 25 / No	Gasoline 8,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Galvanized Steel Impressed Current	Pressurized	<div> <input checked="" type="radio"/>A <input checked="" type="radio"/>B <input checked="" type="radio"/>C <input checked="" type="radio"/>D <input checked="" type="radio"/>E <input checked="" type="radio"/>F <input checked="" type="radio"/>G <input checked="" type="radio"/>H <input checked="" type="radio"/>I <input checked="" type="radio"/>J <input checked="" type="radio"/>K <input checked="" type="radio"/>L </div> <div> <input checked="" type="radio"/>A <input checked="" type="radio"/>B <input checked="" type="radio"/>C <input checked="" type="radio"/>D <input checked="" type="radio"/>E <input checked="" type="radio"/>F <input checked="" type="radio"/>G <input checked="" type="radio"/>H <input checked="" type="radio"/>I <input checked="" type="radio"/>J <input checked="" type="radio"/>K <input checked="" type="radio"/>L </div>	No Yes Yes Yes
2 / 02 Currently in Use	3899	3/26/1981 25 / No	Gasoline 8,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Galvanized Steel Impressed Current	Pressurized	<div> <input checked="" type="radio"/>A <input checked="" type="radio"/>B <input checked="" type="radio"/>C <input checked="" type="radio"/>D <input checked="" type="radio"/>E <input checked="" type="radio"/>F <input checked="" type="radio"/>G <input checked="" type="radio"/>H <input checked="" type="radio"/>I <input checked="" type="radio"/>J <input checked="" type="radio"/>K <input checked="" type="radio"/>L </div> <div> <input checked="" type="radio"/>A <input checked="" type="radio"/>B <input checked="" type="radio"/>C <input checked="" type="radio"/>D <input checked="" type="radio"/>E <input checked="" type="radio"/>F <input checked="" type="radio"/>G <input checked="" type="radio"/>H <input checked="" type="radio"/>I <input checked="" type="radio"/>J <input checked="" type="radio"/>K <input checked="" type="radio"/>L </div>	No Yes Yes Yes
3 / 03 Currently in Use	4920	3/26/1981 25 / No	Gasoline 8,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Galvanized Steel Impressed Current	Pressurized	<div> <input checked="" type="radio"/>A <input checked="" type="radio"/>B <input checked="" type="radio"/>C <input checked="" type="radio"/>D <input checked="" type="radio"/>E <input checked="" type="radio"/>F <input checked="" type="radio"/>G <input checked="" type="radio"/>H <input checked="" type="radio"/>I <input checked="" type="radio"/>J <input checked="" type="radio"/>K <input checked="" type="radio"/>L </div> <div> <input checked="" type="radio"/>A <input checked="" type="radio"/>B <input checked="" type="radio"/>C <input checked="" type="radio"/>D <input checked="" type="radio"/>E <input checked="" type="radio"/>F <input checked="" type="radio"/>G <input checked="" type="radio"/>H <input checked="" type="radio"/>I <input checked="" type="radio"/>J <input checked="" type="radio"/>K <input checked="" type="radio"/>L </div>	No Yes Yes Yes
4 / 04 Currently in Use	4921	3/26/1981 25 / No	Gasoline 8,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Galvanized Steel Impressed Current	Pressurized	<div> <input checked="" type="radio"/>A <input checked="" type="radio"/>B <input checked="" type="radio"/>C <input checked="" type="radio"/>D <input checked="" type="radio"/>E <input checked="" type="radio"/>F <input checked="" type="radio"/>G <input checked="" type="radio"/>H <input checked="" type="radio"/>I <input checked="" type="radio"/>J <input checked="" type="radio"/>K <input checked="" type="radio"/>L </div> <div> <input checked="" type="radio"/>A <input checked="" type="radio"/>B <input checked="" type="radio"/>C <input checked="" type="radio"/>D <input checked="" type="radio"/>E <input checked="" type="radio"/>F <input checked="" type="radio"/>G <input checked="" type="radio"/>H <input checked="" type="radio"/>I <input checked="" type="radio"/>J <input checked="" type="radio"/>K <input checked="" type="radio"/>L </div>	No Yes Yes Yes

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** Kwik Way Inc PO Box 20799 Billings MT 59104 Phone: (406) 656-6310

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5606948	Kwik Way 16	1219 Main St	Billings	59105	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
1 / 01 Currently in Use	3618	4/21/1976 30 / No	Gasoline 10,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Galvanized Steel Cathodically Protected	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
2 / 02 Currently in Use	3619	4/22/1971 35 / No	Gasoline 10,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Galvanized Steel Cathodically Protected	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
3 / 03 Currently in Use	3620	4/22/1971 35 / No	Gasoline 4,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Galvanized Steel Cathodically Protected	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** Reddi Electric Inc PO Box 20272 Billings MT 59104 Phone: (406) 245-3141

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5606953	Reddi Electric Inc	1045 1/2 Central Ave	Billings	59102	(406) 245-3141

TankID/Alt TankID	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection	Piping Release Detection	FR Met
1 / 02 Currently in Use	1837	1/10/1987 19 / No	Gasoline 560	STI-P3 None	Fiberglass Reinforced Plastic None	Safe Suction	<input checked="" type="radio"/> A <input checked="" type="radio"/> B <input type="radio"/> C <input type="radio"/> D <input type="radio"/> E <input type="radio"/> F <input type="radio"/> G <input type="radio"/> H <input type="radio"/> I <input type="radio"/> J <input type="radio"/> K <input type="radio"/> L	<input type="radio"/> B <input type="radio"/> D <input type="radio"/> E <input type="radio"/> F <input type="radio"/> G <input type="radio"/> H <input type="radio"/> I <input checked="" type="radio"/> J <input type="radio"/> K <input type="radio"/> L	Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed



## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** Automatic Car Wash Inc 1133 Grand Ave Billings MT 59102 Phone: (406) 248-2558

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5606956	Dons Car Wash 1st Ave	1924 1st Ave N	Billings	59101	(406) 259-3539

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
5 / 05 Currently in Use	412	11/11/1988 17 / No	Gasoline 10,000	STI-P3 None	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C ● E F G H I J K L</div> <div>● ● E F ● H I J K L</div> </div>	Yes Yes Yes Yes
6 / 06 Currently in Use	413	11/11/1988 17 / No	Gasoline 6,000	STI-P3 None	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C ● E F G H I J K L</div> <div>● ● E F ● H I J K L</div> </div>	Yes Yes Yes Yes
7 / 07 Currently in Use	414	11/11/1988 17 / No	Diesel 6,000	STI-P3 None	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C ● E F G H I J K L</div> <div>● ● E F ● H I J K L</div> </div>	Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** GM Petroleum Dist Inc PO Box 30335 Billings MT 59107 Phone: (406) 252-4661

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5606958	Conomart Superstore 6	2402 Grand Ave	Billings	59102	(406) 656-7775

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
6 / 06 Currently in Use	1161	1/23/1990 16 / No	Gasoline 10,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
7 / 07 Currently in Use	1162	1/23/1990 16 / No	Gasoline 10,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
8 / 08 Currently in Use	1163	1/23/1990 16 / No	Gasoline 8,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** TAG Inc 1320 Main St Billings MT 59105 Phone: (406) 259-3709

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5606960	Heights Conoco 13 UST	1320 Main St	Billings	59105	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
1 / 01 Currently in Use	1164	4/21/1976 30 / No	Gasoline 10,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C D E F G H I J K L</div> <div>B C D E F G H I J K L</div> </div>	Yes Yes Yes Yes
2 / 02 Currently in Use	1165	4/21/1976 30 / No	Gasoline 10,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C D E F G H I J K L</div> <div>B C D E F G H I J K L</div> </div>	Yes Yes Yes Yes
3 / 03 Currently in Use	1166	4/21/1976 30 / No	Gasoline 5,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C D E F G H I J K L</div> <div>B C D E F G H I J K L</div> </div>	Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** GM Petroleum Dist Inc PO Box 30335 Billings MT 59107 Phone: (406) 252-4661

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5606962	GM Petroleum Dist Inc	2100 1st Ave S	Billings	59101	(406) 252-4661

TankID/Alt TankID	Tag Numbe	Installed	Product	Tank Mat'l of Construction	Piping Material	Piping Type	Tank Release Detection	FR Met																									
Status		Age/AST	Capacity	Secondary Option	Secondary Option		Piping Release Detection	Spill/Overl/C																									
1 / 01 Currently in Use	1167	6/1/1985 21 / No	Gasoline 6,000	Asphalt Coated or Bare Steel Impressed Current	Galvanized Steel Impressed Current	Safe Suction	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td>B</td><td></td><td></td><td></td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td><input checked="" type="radio"/></td><td>K</td><td>L</td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	B				D	E	F	G	H	I	<input checked="" type="radio"/>	K	L	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																						
B				D	E	F	G	H	I	<input checked="" type="radio"/>	K	L																					
2 / 02 Currently in Use	1168	6/1/1985 21 / No	Gasoline 6,000	Asphalt Coated or Bare Steel Impressed Current	Galvanized Steel Impressed Current	Safe Suction	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td>B</td><td></td><td></td><td></td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td><input checked="" type="radio"/></td><td>K</td><td>L</td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	B				D	E	F	G	H	I	<input checked="" type="radio"/>	K	L	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																						
B				D	E	F	G	H	I	<input checked="" type="radio"/>	K	L																					
3 / 03 Currently in Use	1169	6/1/1985 21 / No	Diesel 6,000	Asphalt Coated or Bare Steel Impressed Current	Galvanized Steel Impressed Current	Safe Suction	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td>B</td><td></td><td></td><td></td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td><input checked="" type="radio"/></td><td>K</td><td>L</td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	B				D	E	F	G	H	I	<input checked="" type="radio"/>	K	L	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																						
B				D	E	F	G	H	I	<input checked="" type="radio"/>	K	L																					
4 / 04 Currently in Use	4626	6/1/1985 21 / No	Diesel 6,000	Asphalt Coated or Bare Steel Impressed Current	Galvanized Steel Impressed Current	Safe Suction	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td>B</td><td></td><td></td><td></td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td><input checked="" type="radio"/></td><td>K</td><td>L</td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	B				D	E	F	G	H	I	<input checked="" type="radio"/>	K	L	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																						
B				D	E	F	G	H	I	<input checked="" type="radio"/>	K	L																					
5 / 05 Currently In Use	4627	5/7/1983 23 / No	Used Oil 1,000	Asphalt Coated or Bare Steel Impressed Current	Galvanized Steel Impressed Current	Gravity Feed	<table><tr><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td>B</td><td></td><td></td><td></td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td><input checked="" type="radio"/></td><td>L</td></tr></table>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	C	D	E	F	G	H	I	J	K	L	B				D	E	F	G	H	I	J	<input checked="" type="radio"/>	L	Yes Yes Yes Yes
<input checked="" type="radio"/>	<input checked="" type="radio"/>	C	D	E	F	G	H	I	J	K	L																						
B				D	E	F	G	H	I	J	<input checked="" type="radio"/>	L																					

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** S & G Partnership 1225 Mullowney Ln Billings MT 59101 Phone: (406) 252-4661

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5606963	Trading Post Conoco	1225 Mullowney Ln	Billings	59101	(406) 256-8465

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
5 / 05 Currently In Use	4836	5/9/2003 03 / No	Gasoline 12,000	Fiberglass Reinforced Plastic Double-Walled	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
6 / 06 Currently In Use	4837	5/9/2003 03 / No	Gasoline 4,000	Fiberglass Reinforced Plastic Double-Walled	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
7 / 07 Currently In Use	4838	5/9/2003 03 / No	Gasoline 4,000	Fiberglass Reinforced Plastic Double-Walled	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
8 / 08 Currently In Use	4839	5/9/2003 03 / No	Diesel 4,000	Fiberglass Reinforced Plastic Double-Walled	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** GM Petroleum Dist Inc PO Box 30335 Billings MT 59107 Phone: (406) 252-4661

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5606967	Conomart Superstore 5	2701 6th Ave N	Billings	59101	(406) 656-7775

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
1 / 01 Currently in Use	3621	4/22/1968 38 / No	Gasoline 8,000	Asphalt Coated or Bare Steel Lined Interior/Impressed Curr	Galvanized Steel Impressed Current	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
2 / 02 Currently in Use	3622	4/22/1970 36 / No	Gasoline 6,000	Asphalt Coated or Bare Steel Lined Interior/Impressed Curr	Galvanized Steel Impressed Current	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
3 / 03 Currently in Use	3623	4/22/1974 32 / No	Gasoline 6,000	Asphalt Coated or Bare Steel Lined Interior/Impressed Curr	Galvanized Steel Impressed Current	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** Wilson Dunham Service Inc 2511 1st Ave S Billings MT 59101 Phone: (406) 252-0880

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5607756	Wilson Dunham Service Inc	2511 1st Ave S	Billings	59101	(406) 252-0880

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
5 / 05 Currently in Use	2277	11/16/1990 15 / No	Diesel 4,000	STI-P3 None	Fiberglass Reinforced Plastic Double-Walled	Safe Suction	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B <input type="radio"/> D <input type="radio"/> E <input type="radio"/> F <input checked="" type="radio"/> H I <input checked="" type="radio"/> K L</div> </div>	Yes Yes Yes Yes
6 / 06 Currently in Use	2278	11/16/1990 15 / No	Gasoline 4,000	STI-P3 None	Fiberglass Reinforced Plastic Double-Walled	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B <input checked="" type="radio"/> <input type="radio"/> E <input type="radio"/> F <input checked="" type="radio"/> H I <input type="radio"/> J K L</div> </div>	Yes Yes Yes Yes
7 / 07 Currently in Use	2279	11/16/1990 15 / No	Gasoline 4,000	STI-P3 None	Fiberglass Reinforced Plastic Double-Walled	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B <input checked="" type="radio"/> <input type="radio"/> E <input type="radio"/> F <input checked="" type="radio"/> H I <input type="radio"/> J K L</div> </div>	Yes Yes Yes Yes
8 / 08 Currently in Use	2280	11/16/1990 15 / No	Gasoline 8,000	STI-P3 None	Fiberglass Reinforced Plastic Double-Walled	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B <input checked="" type="radio"/> <input type="radio"/> E <input type="radio"/> F <input checked="" type="radio"/> H I <input type="radio"/> J K L</div> </div>	Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** Lynch Flying Service 1691 Aviation PI Billings MT 59105 Phone: (406) 252-0508

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5607797	Lynch Flying Service 5607797	1691 Aviation PI	Billings	59105	(406) 252-0508

TankID/Alt TankID	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction	Piping Material	Piping Type	Tank Release Detection	FR Met																								
Status				Secondary Option	Secondary Option		Piping Release Detection	Spill/Overl/C																								
1 / 10 Currently in Use	1565	10/25/1990 15 / No	Other 20,000	Cathodically Protected Steel Lined Interior	No Piping None	U.S. Suction	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td colspan="4">B</td><td colspan="8">D E F G H I J K L</td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	B				D E F G H I J K L								Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					
B				D E F G H I J K L																												
2 / 11 Currently in Use	1566	10/25/1990 15 / No	Other 20,000	Cathodically Protected Steel None	No Piping None	U.S. Suction	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td colspan="4">B</td><td colspan="8">D E F G H I J K L</td></tr></table>	A	B	C	<input checked="" type="radio"/>	<input checked="" type="radio"/>	F	G	H	I	J	K	L	B				D E F G H I J K L								Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	<input checked="" type="radio"/>	F	G	H	I	J	K	L																					
B				D E F G H I J K L																												
3 / 12 Currently in Use	1567	10/25/1990 15 / No	Gasoline 10,000	Cathodically Protected Steel None	No Piping None	U.S. Suction	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td colspan="4">B</td><td colspan="8">D E F G H I J K L</td></tr></table>	A	B	C	<input checked="" type="radio"/>	<input checked="" type="radio"/>	F	G	H	I	J	K	L	B				D E F G H I J K L								Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	<input checked="" type="radio"/>	F	G	H	I	J	K	L																					
B				D E F G H I J K L																												
11 / 08 Currently in Use	1563	10/25/1990 15 / No	Other 20,000	Cathodically Protected Steel Lined Interior	No Piping None	Not Listed	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td colspan="4">B</td><td colspan="8">D E F G H I J K L</td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	B				D E F G H I J K L								Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					
B				D E F G H I J K L																												
12 / 09 Currently in Use	1564	10/25/1990 15 / No	Other 20,000	Cathodically Protected Steel Lined Interior	No Piping None	Not Listed	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td colspan="4">B</td><td colspan="8">D E F G H I J K L</td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	B				D E F G H I J K L								Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					
B				D E F G H I J K L																												
13 / 13 Currently In Use	1568	6/26/1998 08 / No	Other 20,000	STI-P3 None	No Piping None	U.S. Suction	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td colspan="4">B</td><td colspan="8">D E F G H I J K L</td></tr></table>	A	B	C	<input checked="" type="radio"/>	<input checked="" type="radio"/>	F	G	H	I	J	K	L	B				D E F G H I J K L								Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	<input checked="" type="radio"/>	F	G	H	I	J	K	L																					
B				D E F G H I J K L																												
14 / 14 Currently In Use	1569	6/26/1998 08 / No	Other 20,000	STI-P3 None	No Piping None	U.S. Suction	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td colspan="4">B</td><td colspan="8">D E F G H I J K L</td></tr></table>	A	B	C	<input checked="" type="radio"/>	<input checked="" type="radio"/>	F	G	H	I	J	K	L	B				D E F G H I J K L								Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	<input checked="" type="radio"/>	F	G	H	I	J	K	L																					
B				D E F G H I J K L																												

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed



## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** Rocky Mountain Oil Co Inc 4567 W 80th St PO Box 1224 Minneapolis MN 55440 Phone: (952) 830-8891

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5608058	Holiday Stationstore 266	745 Grand Ave	Billings	59101	(406) 248-7038

TankID/Alt TankID	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction	Piping Material	Piping Type	Tank Release Detection	FR Met																								
Status				Secondary Option	Secondary Option		Piping Release Detection	Spill/Overl/C																								
1 / 08 Currently in Use	3039	6/8/1995 11 / No	Diesel 8,000	Polyethylene Tank Jacket Double-Walled	Flexible Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td colspan="2">B</td><td></td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L	B			<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L																					
B			<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L																					
2 / 05 Currently in Use	3036	6/8/1995 11 / No	Gasoline 12,000	Polyethylene Tank Jacket Double-Walled	Flexible Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td colspan="2">B</td><td></td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L	B			<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L																					
B			<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L																					
3 / 06 Currently in Use	3037	6/8/1995 11 / No	Gasoline 8,000	Polyethylene Tank Jacket Double-Walled	Flexible Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td colspan="2">B</td><td></td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L	B			<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L																					
B			<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L																					
4 / 07 Currently in Use	3038	6/8/1995 11 / No	Gasoline 8,000	Polyethylene Tank Jacket Double-Walled	Flexible Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td colspan="2">B</td><td></td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	B			<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					
B			<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L																					

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** Rocky Mountain Oil Co Inc 4567 W 80th St PO Box 1224 Minneapolis MN 55440 Phone: (952) 830-8891

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5608062	Holiday Stationstore 274	2620 6th Ave N	Billings	59101	(406) 248-7037

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
4 / 04 Currently in Use	3040	10/1/1995 10 / No	Gasoline 8,000	Polyethylene Tank Jacket Double-Walled	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
5 / 05 Currently in Use	4399	10/1/1995 10 / No	Gasoline 8,000	Polyethylene Tank Jacket Double-Walled	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
6 / 06 Currently in Use	3042	10/1/1995 10 / No	Gasoline 10,000	Polyethylene Tank Jacket Double-Walled	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> D E F G H I J K L</div> </div>	Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** Rocky Mountain Oil Co Inc 4567 W 80th St PO Box 1224 Minneapolis MN 55440 Phone: (952) 830-8891

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5608063	Holiday Stationstore 275	105 Broadwater Ave	Billings	59101	(406) 259-7361

TankID/Alt TankID	Tag Numbe	Installed	Product	Tank Mat'l of Construction	Piping Material	Piping Type	Tank Release Detection	FR Met																								
Status		Age/AST	Capacity	Secondary Option	Secondary Option		Piping Release Detection	Spill/Overl/C																								
5 / 05 Currently in Use	3043	7/13/1995 10 / No	Gasoline 8,000	Polyethylene Tank Jacket Double-Walled	Flexible Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td></td><td>E</td><td>F</td><td></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td colspan="2">B</td><td></td><td></td><td>E</td><td>F</td><td></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C		E	F		H	I	J	K	L	B				E	F		H	I	J	K	L	Yes Yes Yes Yes
A	B	C		E	F		H	I	J	K	L																					
B				E	F		H	I	J	K	L																					
6 / 06 Currently in Use	3044	7/13/1995 10 / No	Gasoline 8,000	Polyethylene Tank Jacket Double-Walled	Flexible Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td></td><td>E</td><td>F</td><td></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td colspan="2">B</td><td></td><td></td><td>E</td><td>F</td><td></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C		E	F		H	I	J	K	L	B				E	F		H	I	J	K	L	Yes Yes Yes Yes
A	B	C		E	F		H	I	J	K	L																					
B				E	F		H	I	J	K	L																					
7 / 07 Currently in Use	3045	7/13/1995 10 / No	Gasoline 8,000	Polyethylene Tank Jacket Double-Walled	Flexible Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td></td><td>E</td><td>F</td><td></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td colspan="2">B</td><td></td><td></td><td>E</td><td>F</td><td></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C		E	F		H	I	J	K	L	B				E	F		H	I	J	K	L	Yes Yes Yes Yes
A	B	C		E	F		H	I	J	K	L																					
B				E	F		H	I	J	K	L																					
8 / 08 Currently in Use	3046	7/13/1995 10 / No	Gasoline 8,000	Polyethylene Tank Jacket Double-Walled	Flexible Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td></td><td>E</td><td>F</td><td></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td colspan="2">B</td><td></td><td></td><td>E</td><td>F</td><td></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C		E	F		H	I	J	K	L	B				E	F		H	I	J	K	L	Yes Yes Yes Yes
A	B	C		E	F		H	I	J	K	L																					
B				E	F		H	I	J	K	L																					
9 / 09 Currently in Use	3047	7/13/1995 10 / No	Diesel 8,000	Polyethylene Tank Jacket Double-Walled	Flexible Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td></td><td>E</td><td>F</td><td></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td colspan="2">B</td><td></td><td></td><td>E</td><td>F</td><td></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C		E	F		H	I	J	K	L	B				E	F		H	I	J	K	L	Yes Yes Yes Yes
A	B	C		E	F		H	I	J	K	L																					
B				E	F		H	I	J	K	L																					

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** Cenex Petroleum Inc PO Box 64089 MS 535 Saint Paul MN 55164 Phone: (651) 355-5583

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5608208	Kum and Go Store 824	151 Rosebud Ln	Billings	59101	(406) 259-5426

TankID/Alt TankID	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction	Piping Material		Tank Release Detection	FR Met																									
Status				Secondary Option	Secondary Option	Piping Type	Piping Release Detection	Spill/Overl/C																									
1 / 01 Currently in Use	577	5/7/1978 28 / No	Gasoline 12,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Bare Steel Cathodically Protected	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td colspan="4">B</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	B				<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																						
B				<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					
2 / 02 Currently in Use	578	5/7/1978 28 / No	Gasoline 12,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Bare Steel Cathodically Protected	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td colspan="4">B</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	B				<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																						
B				<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					
3 / 03 Currently in Use	579	5/7/1978 28 / No	Diesel 10,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Bare Steel Cathodically Protected	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td colspan="4">B</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	B				<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																						
B				<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					
4 / 04 Currently in Use	580	5/7/1978 28 / No	Gasoline 12,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Bare Steel Cathodically Protected	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td colspan="4">B</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	B				<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																						
B				<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					
5 / 05 Currently in Use	581	11/1/1992 13 / No	Diesel 10,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td colspan="4">B</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	B				<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																						
B				<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					
6 / 06 Currently in Use	582	11/1/1992 13 / No	Diesel 12,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td colspan="4">B</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	B				<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																						
B				<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** Cenex Petroleum Inc PO Box 64089 MS 535 Saint Paul MN 55164 Phone: (651) 355-5583

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5608209	Kum and Go Store 828	610 Wicks Ln	Billings	59105	(406) 259-7054

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
4 / 04 Currently In Use	4256	1/1/1999 07 / No	Gasoline 12,000	STI-P3 None	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div>	Yes Yes Yes Yes
5 / 05 Currently In Use	4257	1/1/1999 07 / No	Gasoline 10,000	STI-P3 None	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div>	Yes Yes Yes Yes
6 / 06 Currently In Use	4258	1/1/1999 07 / No	Diesel 5,000	STI-P3 None	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div>	Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** Market Basket Store 8014 S Frontage Road Billings MT 59101 Phone: (406) 656-3546

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5608286	Market Basket Store	8014 S Frontage Road	Billings	59101	(406) 656-3546

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
1 / 03 Currently In Use	3314	10/6/1995 10 / No	Gasoline 8,000	STI-P3 None	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B <input checked="" type="radio"/> E F <input checked="" type="radio"/> H I J K L</div> </div>	Yes Yes Yes Yes
2 / 04 Currently In Use	3315	10/6/1995 10 / No	Gasoline 4,000	STI-P3 None	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B <input checked="" type="radio"/> E F <input checked="" type="radio"/> H I J K L</div> </div>	Yes Yes Yes Yes
5 / 05 Currently In Use	4945	11/28/2003 02 / No	Diesel 8,000	STI-P3 None	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B <input checked="" type="radio"/> E F <input checked="" type="radio"/> H I J K L</div> </div>	Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** Hilands Golf Club Inc 714 Poly Dr Billings MT 59102 Phone: (406) 245-3049

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5608312	Hilands Golf Club Inc Maintenance Facilit	714 Poly Dr	Billings	59102	(406) 252-9474

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
2 / 02 Currently in Use	1373	5/6/1991 15 / No	Gasoline 750	STI-P3 None	Fiberglass Reinforced Plastic None	Safe Suction	<div> <input checked="" type="radio"/> A <input type="radio"/> B <input type="radio"/> C <input type="radio"/> D <input type="radio"/> E <input type="radio"/> F <input type="radio"/> G <input type="radio"/> H <input type="radio"/> I <input type="radio"/> J <input type="radio"/> K <input type="radio"/> L                 </div> <div> <input type="radio"/> B <input type="radio"/> D <input type="radio"/> E <input type="radio"/> F <input type="radio"/> G <input type="radio"/> H <input type="radio"/> I <input checked="" type="radio"/> K <input type="radio"/> L                 </div>	Yes Yes Yes Yes
3 / 03 Currently in Use	1374	5/6/1991 15 / No	Diesel 250	STI-P3 None	Fiberglass Reinforced Plastic None	Safe Suction	<div> <input checked="" type="radio"/> A <input type="radio"/> B <input type="radio"/> C <input type="radio"/> D <input type="radio"/> E <input type="radio"/> F <input type="radio"/> G <input type="radio"/> H <input type="radio"/> I <input type="radio"/> J <input type="radio"/> K <input type="radio"/> L                 </div> <div> <input type="radio"/> B <input type="radio"/> D <input type="radio"/> E <input type="radio"/> F <input type="radio"/> G <input type="radio"/> H <input type="radio"/> I <input checked="" type="radio"/> K <input type="radio"/> L                 </div>	Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** Pepsi Cola Bottling Co 344 Howard Ave Billings MT 59101 Phone: (406) 252-9355

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5608323	Pepsi Cola Bottling Co Billings	344 Howard Ave	Billings	59101	(406) 252-9355

TankID/Alt TankID	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection	Piping Release Detection	FR Met
1 / 03 Currently in Use	1798	8/1/1990 15 / No	Gasoline 3,000	STI-P3 None	Galvanized Steel Cathodically Protected	Safe Suction	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F G H I <input checked="" type="radio"/> K L</div> </div>	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F G H I <input checked="" type="radio"/> K L</div> </div>	No Yes Yes Yes

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed



## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** GM Petroleum Dist Inc PO Box 30335 Billings MT 59107 Phone: (406) 252-4661

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5608324	GM Petroleum Dist Inc Kardlock Site II	S 36th St & 1st Ave S	Billings	59101	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
1 / 01 Currently in Use	1179	5/6/1978 28 / No	Diesel 10,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Bare Steel Impressed Current	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
2 / 02 Currently in Use	1180	5/6/1978 28 / No	Diesel 8,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Bare Steel Impressed Current	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
3 / 03 Currently in Use	1181	5/6/1978 28 / No	Gasoline 8,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Bare Steel Impressed Current	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** Gordon Vandiviere 942 Broadwater Ave Billings MT 59101 Phone: (406) 245-4924

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5608671	Korner Stop	942 Broadwater Ave	Billings	59101	(406) 245-4924

TankID/Alt TankID	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction	Piping Material		Tank Release Detection	FR Met																						
Status				Secondary Option	Secondary Option	Piping Type	Piping Release Detection	Spill/Overl/C																						
2 / 05 Currently in Use	3170	12/1/1993 12 / No	Gasoline 8,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<table><tr><td>A</td><td><input checked="" type="radio"/></td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td><input checked="" type="radio"/></td><td></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td><td></td></tr></table>	A	<input checked="" type="radio"/>	D	E	F	G	H	I	J	K	L	<input checked="" type="radio"/>		E	F	G	H	I	J	K	L		Yes Yes Yes Yes
A	<input checked="" type="radio"/>	D	E	F	G	H	I	J	K	L																				
<input checked="" type="radio"/>		E	F	G	H	I	J	K	L																					
5 / 04 Currently in Use	3169	12/1/1993 12 / No	Gasoline 8,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<table><tr><td>A</td><td><input checked="" type="radio"/></td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td><input checked="" type="radio"/></td><td></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td><td></td></tr></table>	A	<input checked="" type="radio"/>	D	E	F	G	H	I	J	K	L	<input checked="" type="radio"/>		E	F	G	H	I	J	K	L		Yes Yes Yes Yes
A	<input checked="" type="radio"/>	D	E	F	G	H	I	J	K	L																				
<input checked="" type="radio"/>		E	F	G	H	I	J	K	L																					

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** Qwest Communications 1600 7th Ave Room 2206 Seattle WA 98191 Phone: (206) 346-7532

<b>Sys Fac I</b>	<b>Location Name</b>	<b>Location Street Address</b>	<b>Location City</b>	<b>Zip</b>	<b>Location Phone</b>
5608761	Qwest Billings Garage	219 Calhoun Ln	Billings	59101	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
2 / 02 Currently in Use	1732	5/1/1993 13 / No	Gasoline 6,000	Fiberglass Reinforced Plastic Double-Walled	Fiberglass Reinforced Plastic Double-Walled	Pressurized	<div style="display: flex; justify-content: space-between; padding: 2px;"> <span>(A) (B) (C) (D) (E) (F) (G) (H) (I) (J) (K) (L)</span> </div> <div style="display: flex; justify-content: space-between; padding: 2px;"> <span>(B) (D) (E) (F) (G) (H) (I) (J) (K) (L)</span> </div>	Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** Qwest Communications 1600 7th Ave Room 2206 Seattle WA 98191 Phone: (206) 346-7532

<b>Sys Fac I</b>	<b>Location Name</b>	<b>Location Street Address</b>	<b>Location City</b>	<b>Zip</b>	<b>Location Phone</b>
5608762	Qwest Billings West Central Office	3190 Central Ave	Billings	59102	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
2 / 02 Currently in Use	1733	11/1/1994 11 / No	Diesel 1,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	U.S. Suction	<div style="display: flex; flex-wrap: wrap; padding: 2px;"> <div style="margin: 2px;">A B C <input checked="" type="radio"/> E F <input checked="" type="radio"/> H I J K L</div> <div style="margin: 2px;">B D E F <input checked="" type="radio"/> H I J K L</div> </div>	Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** Cenex Petroleum Inc PO Box 64089 MS 535 Saint Paul MN 55164 Phone: (651) 355-5583

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5608903	Kum and Go Store 822	1201 Central Ave	Billings	59102	(406) 245-9670

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
1 / 01 Currently in Use	586	10/3/1968 37 / No	Gasoline 10,000	Asphalt Coated or Bare Steel Lined Interior/Impressed Curr	Fiberglass Reinforced Plastic None	Safe Suction	<div> <div>A B C <input checked="" type="radio"/> E F G H I <input checked="" type="radio"/> K L</div> <div><input checked="" type="radio"/> D E F G H I J K L</div> </div>	Yes Yes Yes Yes
2 / 02 Currently in Use	587	10/3/1968 37 / No	Gasoline 4,000	Asphalt Coated or Bare Steel Lined Interior/Impressed Curr	Fiberglass Reinforced Plastic None	Safe Suction	<div> <div>A B C <input checked="" type="radio"/> E F G H I <input checked="" type="radio"/> K L</div> <div><input checked="" type="radio"/> D E F G H I J K L</div> </div>	Yes Yes Yes Yes
3 / 03 Currently in Use	588	10/3/1968 37 / No	Gasoline 4,000	Asphalt Coated or Bare Steel Lined Interior/Impressed Curr	Fiberglass Reinforced Plastic None	Safe Suction	<div> <div>A B C <input checked="" type="radio"/> E F G H I <input checked="" type="radio"/> K L</div> <div><input checked="" type="radio"/> D E F G H I J K L</div> </div>	Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** Cenex Petroleum Inc PO Box 64089 MS 535 Saint Paul MN 55164 Phone: (651) 355-5583

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5608904	Kum and Go Store 825	236 Main St	Billings	59105	(406) 259-3240

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
1 / 01 Currently in Use	589	10/3/1982 23 / No	Gasoline 12,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F G H I J K <input checked="" type="radio"/></div> </div>	Yes Yes Yes Yes
2 / 02 Currently in Use	590	10/3/1982 23 / No	Gasoline 12,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F G H I J K <input checked="" type="radio"/></div> </div>	Yes Yes Yes Yes
3 / 03 Currently in Use	591	10/3/1982 23 / No	Diesel 12,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F G H I J K <input checked="" type="radio"/></div> </div>	Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** Sysco Food Services of Montana PO Box 31198 Billings MT 59107 Phone: (406) 247-1131

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5609271	Sysco Food Services of Montana Daniels	275 Daniels St	Billings	59101	(406) 247-1136

TankID/Alt TankID	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction	Piping Material	Piping Type	Tank Release Detection	FR Met																									
Status				Secondary Option	Secondary Option		Piping Release Detection	Spill/Overl/C																									
1 / 01 Currently in Use	4716	1/1/1993 13 / No	Diesel 12,000	Fiberglass Reinforced Plastic Double-Walled	Fiberglass Reinforced Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td colspan="3">B</td><td><input checked="" type="radio"/></td><td colspan="2">E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L	B			<input checked="" type="radio"/>	E		F	<input checked="" type="radio"/>	H	I	J	K	L	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L																						
B			<input checked="" type="radio"/>	E		F	<input checked="" type="radio"/>	H	I	J	K	L																					
2 / 02 Currently in Use	4717	1/1/1993 13 / No	Diesel 8,000	Fiberglass Reinforced Plastic Double-Walled	Fiberglass Reinforced Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td colspan="3">B</td><td><input checked="" type="radio"/></td><td colspan="2">E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L	B			<input checked="" type="radio"/>	E		F	<input checked="" type="radio"/>	H	I	J	K	L	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L																						
B			<input checked="" type="radio"/>	E		F	<input checked="" type="radio"/>	H	I	J	K	L																					

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** Montana Department of Transportation      Deadhead   Helena   MT   59620   Phone: (406) 444-6200

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5609501	MDOT Billings Site	424 Morey St	Billings	59101	

TankID/Alt TankID	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction	Piping Material		Tank Release Detection	FR Met																								
Status				Secondary Option	Secondary Option	Piping Type	Piping Release Detection	Spill/Overl/C																								
1 / 06 Currently in Use	2948	9/1/1993 12 / No	Gasoline 10,000	Cathodically Protected Steel None	Fiberglass Reinforced Plastic None	Safe Suction	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td colspan="2">B</td><td colspan="2">D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td><input checked="" type="radio"/></td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	B		D		E	F	G	H	I	J	K	<input checked="" type="radio"/>	No Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					
B		D		E	F	G	H	I	J	K	<input checked="" type="radio"/>																					
2 / 07 Currently in Use	2949	9/1/1993 12 / No	Diesel 10,000	Cathodically Protected Steel None	Fiberglass Reinforced Plastic None	Safe Suction	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td colspan="2">B</td><td colspan="2">D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td><input checked="" type="radio"/></td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	B		D		E	F	G	H	I	J	K	<input checked="" type="radio"/>	No Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					
B		D		E	F	G	H	I	J	K	<input checked="" type="radio"/>																					

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed



## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** Rocky Mountain Oil Co Inc 4567 W 80th St PO Box 1224 Minneapolis MN 55440 Phone: (952) 830-8891

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5609695	Holiday Stationstore 280	1020 Main St	Billings	59105	(406) 245-1254

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
1 / 01 Currently in Use	3048	4/1/1987 19 / No	Gasoline 12,000	STI-P3 None	Galvanized Steel Cathodically Protected	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
2 / 02 Currently in Use	3049	4/1/1987 19 / No	Gasoline 12,000	STI-P3 None	Galvanized Steel Cathodically Protected	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
3 / 03 Currently in Use	3050	4/1/1987 19 / No	Gasoline 8,000	STI-P3 None	Galvanized Steel Cathodically Protected	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
4 / 04 Currently in Use	3051	4/1/1987 19 / No	Diesel 8,000	STI-P3 None	Galvanized Steel Cathodically Protected	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** City of Billings Fire Dept 2305 8th Ave N Billings MT 59101 Phone: (406) 657-8422

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5609739	Billings Fire Dept Station 1	2305 8th Ave N	Billings	59101	(406) 657-8423

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
1 / 04 Currently in Use	2729	12/1/1993 12 / No	Gasoline 517	STI-P3 None	Copper Double-Walled/Non-Corro	Safe Suction	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F G H I <input checked="" type="radio"/> K L</div> </div>	Yes Yes Yes Yes
2 / 03 Currently in Use	2728	12/1/1993 12 / No	Diesel 1,035	STI-P3 None	Copper Double-Walled/Non-Corro	U.S. Suction	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I <input checked="" type="radio"/> K L</div> </div>	Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** City of Billings Fire Dept 2305 8th Ave N Billings MT 59101 Phone: (406) 657-8422

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5609740	Billings Fire Station 2	501 S 28th St	Billings	59101	

TankID/Alt TankID	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction	Piping Material	Piping Type	Tank Release Detection	FR Met																										
Status				Secondary Option	Secondary Option		Piping Release Detection	Spill/Overl/C																										
2 / 03 Currently in Use	3699	6/12/1990 16 / No	Diesel 1,000	STI-P3 None	Bare Steel Cathodically Protected	Safe Suction	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td colspan="3">B</td><td colspan="3">D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td><input checked="" type="radio"/></td><td>K</td><td>L</td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	B			D			E	F	G	H	I	<input checked="" type="radio"/>	K	L	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																							
B			D			E	F	G	H	I	<input checked="" type="radio"/>	K	L																					
4 / 04 Currently in Use	3700	6/12/1990 16 / No	Gasoline 1,000	STI-P3 None	Bare Steel Cathodically Protected	Safe Suction	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td colspan="3">B</td><td colspan="3">D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td><input checked="" type="radio"/></td><td>K</td><td>L</td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	B			D			E	F	G	H	I	<input checked="" type="radio"/>	K	L	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																							
B			D			E	F	G	H	I	<input checked="" type="radio"/>	K	L																					

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** City of Billings Fire Dept 2305 8th Ave N Billings MT 59101 Phone: (406) 657-8422

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5609741	Billings Fire Station 3	1928 17th St W	Billings	59102	

TankID/Alt TankID	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection	Piping Release Detection	FR Met
2 / 02 Currently in Use	4297	3/1/1992 14 / No	Diesel 500	STI-P3 None	Fiberglass Reinforced Plastic None	Safe Suction	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F G H I <input checked="" type="radio"/> K L</div> </div>	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F G H I <input checked="" type="radio"/> K L</div> </div>	Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** City of Billings Fire Dept 2305 8th Ave N Billings MT 59101 Phone: (406) 657-8422

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5609742	Billings Fire Station 5	605 S 24th St W	Billings	59102	

TankID/Alt TankID	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction	Piping Material	Piping Type	Tank Release Detection	FR Met																									
Status				Secondary Option	Secondary Option		Piping Release Detection	Spill/Overl/C																									
4 / 04 Currently in Use	2731	1/1/1993 13 / No	Gasoline 517	STI-P3 None	Fiberglass Reinforced Plastic None	Safe Suction	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td colspan="3">B</td><td colspan="3">D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td><input checked="" type="radio"/>K</td><td>L</td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	B			D			E	F	G	H	I	<input checked="" type="radio"/> K	L	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																						
B			D			E	F	G	H	I	<input checked="" type="radio"/> K	L																					
5 / 05 Currently in Use	2732	1/1/1993 13 / No	Diesel 517	STI-P3 None	Fiberglass Reinforced Plastic None	Safe Suction	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td colspan="3">B</td><td colspan="3">D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td><input checked="" type="radio"/>K</td><td>L</td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	B			D			E	F	G	H	I	<input checked="" type="radio"/> K	L	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																						
B			D			E	F	G	H	I	<input checked="" type="radio"/> K	L																					

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** City of Billings Fire Dept 2305 8th Ave N Billings MT 59101 Phone: (406) 657-8422

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5609743	Billings Fire Station 6	1601 St Andrews Dr	Billings	59105	

TankID/Alt TankID	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection	Piping Release Detection	FR Met
1 / 01 Currently in Use	2733	10/19/1987 18 / No	Diesel 500	STI-P3 None	Fiberglass Reinforced Plastic None	Safe Suction	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F G H I <input checked="" type="radio"/> K L</div> </div>	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F G H I <input checked="" type="radio"/> K L</div> </div>	Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** City of Billings Purchasing 1901 Terminal Circle RM216 PO Box 1178 Billings MT 59103 Phone: (406) 657-8495

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5609744	City Landfill	5240 Jellison Road	Billings	59101	(406) 245-7193

TankID/Alt TankID	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection	Piping Release Detection	FR Met
1 / 01 Currently in Use	630	10/1/1986 19 / No	Diesel 10,000	STI-P3 Double-Walled	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div>	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div>	Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** City of Billings Purchasing 1901 Terminal Circle RM216 PO Box 1178 Billings MT 59103 Phone: (406) 657-8495

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5609746	Public Utilities Dept	2251 Belknap Ave	Billings	59101	(406) 657-8335

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
1 / 04 Currently in Use	631	1/1/1990 16 / No	Gasoline 10,000	Composite (Steel w/ FRP) None	Fiberglass Reinforced Plastic None	U.S. Suction	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> D E F G H I J K L</div> </div>	Yes Yes Yes Yes
2 / 05 Currently in Use	632	1/1/1990 16 / No	Diesel 10,000	Composite (Steel w/ FRP) None	Fiberglass Reinforced Plastic None	U.S. Suction	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> D E F G H I J K L</div> </div>	Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed



## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** City of Billings Purchasing 1901 Terminal Circle RM216 PO Box 1178 Billings MT 59103 Phone: (406) 657-8495

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5609747	Billings Metropolitan Transit	1705 Monad Road	Billings	59102	(406) 657-8218

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
3 / 03 Currently In Use	635	10/15/1983 22 / No	Used Oil 2,000	Cathodically Protected Steel None	Flexible Plastic None	Gravity Feed	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> D E F G H I J K L</div> </div>	Yes Yes Yes Yes
4 / 04 Currently In Use	4862	9/3/2003 02 / No	Diesel 8,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
5 / 05 Currently In Use	4863	9/3/2003 02 / No	Diesel 8,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** Rocky Mountain Oil Co Inc 4567 W 80th St PO Box 1224 Minneapolis MN 55440 Phone: (952) 830-8891

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5609752	Holiday Stationstore 284	3226 Rosebud Dr	Billings	59102	(406) 652-4095

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
1 / 01 Currently in Use	3052	11/5/1983 22 / No	Gasoline 10,000	STI-P3 Impressed Current	Bare Steel Impressed Current	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H <input checked="" type="radio"/> J K L</div> <div>B <input checked="" type="radio"/> E F G H <input checked="" type="radio"/> J K L</div> </div>	Yes Yes Yes Yes
2 / 02 Currently in Use	3053	11/5/1983 22 / No	Gasoline 10,000	STI-P3 Impressed Current	Bare Steel Impressed Current	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H <input checked="" type="radio"/> J K L</div> <div>B <input checked="" type="radio"/> E F G H <input checked="" type="radio"/> J K L</div> </div>	Yes Yes Yes Yes
3 / 03 Currently in Use	3054	11/5/1983 22 / No	Gasoline 6,000	STI-P3 Impressed Current	Bare Steel Impressed Current	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H <input checked="" type="radio"/> J K L</div> <div>B <input checked="" type="radio"/> E F G H <input checked="" type="radio"/> J K L</div> </div>	Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** Rocky Mountain Oil Co Inc 4567 W 80th St PO Box 1224 Minneapolis MN 55440 Phone: (952) 830-8891

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5609753	Holiday Stationstore 285	785 S 20th St W	Billings	59102	(406) 656-3430

TankID/Alt TankID	Tag Numbe	Installed	Product	Tank Mat'l of Construction	Piping Material	Piping Type	Tank Release Detection	FR Met																								
Status		Age/AST	Capacity	Secondary Option	Secondary Option		Piping Release Detection	Spill/Overl/C																								
5 / 05 Currently In Use	3055	4/1/1997 09 / No	Gasoline 8,000	Polyethylene Tank Jacket Double-Walled	Flexible Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td>B</td><td></td><td></td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	B			<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					
B			<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L																					
6 / 06 Currently In Use	3056	4/1/1997 09 / No	Gasoline 8,000	Polyethylene Tank Jacket Double-Walled	Flexible Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td>B</td><td></td><td></td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	B			<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					
B			<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L																					
7 / 07 Currently In Use	3057	4/1/1997 09 / No	Gasoline 8,000	Polyethylene Tank Jacket Double-Walled	Flexible Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td>B</td><td></td><td></td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	B			<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					
B			<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L																					
8 / 08 Currently In Use	3058	4/1/1997 09 / No	Gasoline 8,000	Polyethylene Tank Jacket Double-Walled	Flexible Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td>B</td><td></td><td></td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	B			<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					
B			<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L																					
9 / 09 Currently In Use	3059	4/1/1997 09 / No	Diesel 8,000	Polyethylene Tank Jacket Double-Walled	Flexible Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td>B</td><td></td><td></td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	B			<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					
B			<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L																					

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** Rocky Mountain Oil Co Inc 4567 W 80th St PO Box 1224 Minneapolis MN 55440 Phone: (952) 830-8891

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5609754	Holiday Stationstore 286	405 Alkali Creek Road	Billings	59105	(406) 248-3466

TankID/Alt TankID	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction	Piping Material	Piping Type	Tank Release Detection	FR Met																								
Status				Secondary Option	Secondary Option		Piping Release Detection	Spill/Overl/C																								
1 / 01 Currently in Use	3060	6/1/1984 22 / No	Gasoline 10,000	Asphalt Coated or Bare Steel Impressed Current	Galvanized Steel Impressed Current	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td><input checked="" type="radio"/></td><td>J</td><td>K</td><td>L</td></tr><tr><td>B</td><td></td><td></td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td><input checked="" type="radio"/></td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	<input checked="" type="radio"/>	J	K	L	B			<input checked="" type="radio"/>	E	F	G	H	<input checked="" type="radio"/>	J	K	L	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	G	H	<input checked="" type="radio"/>	J	K	L																					
B			<input checked="" type="radio"/>	E	F	G	H	<input checked="" type="radio"/>	J	K	L																					
2 / 02 Currently in Use	3061	6/1/1984 22 / No	Gasoline 10,000	Asphalt Coated or Bare Steel Impressed Current	Galvanized Steel Impressed Current	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td><input checked="" type="radio"/></td><td>J</td><td>K</td><td>L</td></tr><tr><td>B</td><td></td><td></td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td><input checked="" type="radio"/></td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	<input checked="" type="radio"/>	J	K	L	B			<input checked="" type="radio"/>	E	F	G	H	<input checked="" type="radio"/>	J	K	L	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	G	H	<input checked="" type="radio"/>	J	K	L																					
B			<input checked="" type="radio"/>	E	F	G	H	<input checked="" type="radio"/>	J	K	L																					

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** Stockton Oil Co 1607 4th Ave N PO Box 1756 Billings MT 59103 Phone: (406) 245-6376

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5610075	Kwik Way 22	3189 King Ave W	Billings	59102	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
1 / 01 Currently in Use	3834	1/13/1987 19 / No	Gasoline 8,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C D E F G H J K L</div> <div> <input checked="" type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> </div> </div>	Yes Yes Yes Yes
2 / 02 Currently in Use	3835	1/13/1987 19 / No	Gasoline 6,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C D E F G H J K L</div> <div> <input checked="" type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> </div> </div>	Yes Yes Yes Yes
3 / 03 Currently in Use	3836	1/13/1987 19 / No	Gasoline 6,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C D E F G H J K L</div> <div> <input checked="" type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> </div> </div>	Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** Federal Aviation Admin 1540 Lake Elmo Dr Ste 6 Billings MT 59105 Phone: (406) 657-6981

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5610283	Federal Aviation Admin Billings Generato	1540 Lake Elmo Dr Ste N6	Billings	59105	(406) 657-6981

TankID/Alt TankID	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C																									
1 / 01 Currently in Use	1051	1/26/1990 16 / No	Diesel 1,000	Fiberglass Reinforced Plastic Double-Walled	Copper Double-Walled/Non-Corro	U.S. Suction	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td></td><td><input checked="" type="radio"/></td><td></td><td></td><td>D</td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L		<input checked="" type="radio"/>			D	E	F	<input checked="" type="radio"/>	H	I	J	K	L	No Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																						
	<input checked="" type="radio"/>			D	E	F	<input checked="" type="radio"/>	H	I	J	K	L																					

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** Billings Public Schools Dist 2      415 N 30th St   Billings   MT   59101   Phone: (406) 247-3777

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5610585	Skyview High School Dist 2	1775 High Sierra Blvd	Billings	59105	(406) 247-2300

TankID/Alt TankID	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection	Piping Release Detection	FR Met
1 / S1 Currently in Use	448	3/16/1987 19 / No	Heating Oil 5,000	STI-P3 None	Flexible Plastic Double-Walled	U.S. Suction	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div>	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div>	Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** SNG Inc 4410 State Ave Billings MT 59101 Phone: (406) 245-0161

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5610797	3 Gs Convenience Center 27th St	702 S 27th St	Billings	59101	

TankID/Alt TankID	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction	Piping Material	Piping Type	Tank Release Detection	FR Met																								
Status				Secondary Option	Secondary Option		Piping Release Detection	Spill/Overl/C																								
4 / 04 Currently In Use	4751	7/1/1998 08 / No	Gasoline 8,000	STI-P3 None	Flexible Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>●</td><td>J</td><td>K</td><td>L</td></tr><tr><td>●</td><td></td><td></td><td>●</td><td>E</td><td>F</td><td>G</td><td>H</td><td>●</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	D	E	F	G	H	●	J	K	L	●			●	E	F	G	H	●	J	K	L	Yes Yes Yes Yes
A	B	C	D	E	F	G	H	●	J	K	L																					
●			●	E	F	G	H	●	J	K	L																					
5 / 05 Currently In Use	4752	7/1/1998 08 / No	Gasoline 4,000	STI-P3 None	Flexible Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>●</td><td>J</td><td>K</td><td>L</td></tr><tr><td>●</td><td></td><td></td><td>●</td><td>E</td><td>F</td><td>G</td><td>H</td><td>●</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	D	E	F	G	H	●	J	K	L	●			●	E	F	G	H	●	J	K	L	Yes Yes Yes Yes
A	B	C	D	E	F	G	H	●	J	K	L																					
●			●	E	F	G	H	●	J	K	L																					

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed



## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** TLC Enterprises Inc PO Box 549 Billings MT 59103 Phone: (406) 245-4531

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5610866	Gas N Go	800 Jackson St	Billings	59101	(406) 245-1133

TankID/Alt TankID	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection	Piping Release Detection	FR Met
1 / 01 Currently in Use	4551	4/10/1984 22 / No	Gasoline 6,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Galvanized Steel Impressed Current	Safe Suction	<div> <div>A</div> <div><input checked="" type="radio"/></div> <div>D</div> <div>E</div> <div>F</div> <div>G</div> <div>H</div> <div>I</div> <div>J</div> <div>K</div> <div>L</div> </div>	<div> <div>B</div> <div>D</div> <div>E</div> <div>F</div> <div>G</div> <div>H</div> <div>I</div> <div><input checked="" type="radio"/></div> <div>K</div> <div>L</div> </div>	<div>Yes</div> <div>Yes</div> <div>Yes</div> <div>Yes</div>

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** Exxon Terminal 607 Exxon Mobil Road Billings MT 59101 Phone: (406) 657-5400

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5611335	Exxon Marketing Billings Terminal	607 Exxon Refinery Road	Billings	59101	(406) 657-5400

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
1 / S16 Currently in Use			Other 4,000	Asphalt Coated or Bare Steel None	Bare Steel Cathodically Protected	Not Listed	<div> <div>A B C D E F G H I J K L</div> <div>B D E F G H I J K L</div> </div>	Yes Yes Yes Yes
2 / 37 Currently in Use	2736	10/1/1994 11 / No	Mixture 3,000	Composite (Steel w/ FRP) Double-Walled	Bare Steel Impressed Current	Gravity Feed	<div> <div>A B C D E F G H I J K L</div> <div>B D E F G H I J K L</div> </div>	Yes Yes Yes Yes
3 / S01 Currently in Use	2737	1/1/1950 56 / Ye	Gasoline 197,000	Unknown Impressed Current	Galvanized Steel Impressed Current	Pressurized	<div> <div>A B C D E F G H I J K L</div> <div>B D E F G H I J K L</div> </div>	Yes Yes Yes Yes
4 / S02 Currently in Use	2738	1/1/1950 56 / Ye	Gasoline 197,000	Unknown Impressed Current	Galvanized Steel Impressed Current	Pressurized	<div> <div>A B C D E F G H I J K L</div> <div>B D E F G H I J K L</div> </div>	Yes Yes Yes Yes
5 / S03 Currently in Use	2739	1/1/1950 56 / Ye	Diesel 60,000	Unknown Impressed Current	Galvanized Steel Impressed Current	Pressurized	<div> <div>A B C D E F G H I J K L</div> <div>B D E F G H I J K L</div> </div>	Yes Yes Yes Yes
6 / S04 Currently in Use	2740	1/1/1950 56 / Ye	Diesel 60,000	Unknown Impressed Current	Galvanized Steel Impressed Current	Pressurized	<div> <div>A B C D E F G H I J K L</div> <div>B D E F G H I J K L</div> </div>	Yes Yes Yes Yes
7 / S05 Currently in Use	2741	1/1/1950 56 / Ye	Diesel 60,000	Unknown Impressed Current	Galvanized Steel Impressed Current	Pressurized	<div> <div>A B C D E F G H I J K L</div> <div>B D E F G H I J K L</div> </div>	Yes Yes Yes Yes
8 / S06 Currently in Use	2742	1/1/1950 56 / Ye	Diesel 60,000	Unknown Impressed Current	Galvanized Steel Impressed Current	Pressurized	<div> <div>A B C D E F G H I J K L</div> <div>B D E F G H I J K L</div> </div>	Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Yellowstone

13 / S11 Currently in Use	2747	1/1/1950 56 / Ye	Gasoline 60,000	Unknown Impressed Current	Galvanized Steel Impressed Current	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td><b>K</b></td><td>L</td></tr><tr><td><b>B</b></td><td></td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td><td></td></tr></table>	A	B	C	D	E	F	G	H	I	J	<b>K</b>	L	<b>B</b>		D	E	F	G	H	I	J	K	L		Yes Yes Yes Yes
A	B	C	D	E	F	G	H	I	J	<b>K</b>	L																					
<b>B</b>		D	E	F	G	H	I	J	K	L																						
14 / S12 Currently in Use	2748	1/1/1950 56 / Ye	Diesel 60,000	Unknown Impressed Current	Galvanized Steel Impressed Current	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td><b>K</b></td><td>L</td></tr><tr><td><b>B</b></td><td></td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td><td></td></tr></table>	A	B	C	D	E	F	G	H	I	J	<b>K</b>	L	<b>B</b>		D	E	F	G	H	I	J	K	L		Yes Yes Yes Yes
A	B	C	D	E	F	G	H	I	J	<b>K</b>	L																					
<b>B</b>		D	E	F	G	H	I	J	K	L																						
15 / S13 Currently in Use	2749	1/1/1950 56 / Ye	Diesel 60,000	Unknown Impressed Current	Galvanized Steel Impressed Current	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td><b>L</b></td></tr><tr><td><b>B</b></td><td></td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td><td></td></tr></table>	A	B	C	D	E	F	G	H	I	J	K	<b>L</b>	<b>B</b>		D	E	F	G	H	I	J	K	L		Yes Yes Yes Yes
A	B	C	D	E	F	G	H	I	J	K	<b>L</b>																					
<b>B</b>		D	E	F	G	H	I	J	K	L																						
16 / S14 Currently in Use	2750	1/1/1950 56 / Ye	Gasoline 60,000	Unknown Impressed Current	Galvanized Steel Impressed Current	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td><b>L</b></td></tr><tr><td><b>B</b></td><td></td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td><td></td></tr></table>	A	B	C	D	E	F	G	H	I	J	K	<b>L</b>	<b>B</b>		D	E	F	G	H	I	J	K	L		Yes Yes Yes Yes
A	B	C	D	E	F	G	H	I	J	K	<b>L</b>																					
<b>B</b>		D	E	F	G	H	I	J	K	L																						
36 / S34 Currently in Use	2764	1/1/1952 54 / Ye	Gasoline 2,959,110	Unknown Impressed Current	Galvanized Steel Impressed Current	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td><b>K</b></td><td>L</td></tr><tr><td><b>B</b></td><td></td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td><td></td></tr></table>	A	B	C	D	E	F	G	H	I	J	<b>K</b>	L	<b>B</b>		D	E	F	G	H	I	J	K	L		Yes Yes Yes Yes
A	B	C	D	E	F	G	H	I	J	<b>K</b>	L																					
<b>B</b>		D	E	F	G	H	I	J	K	L																						
37 / S35 Currently in Use	2765	1/1/1952 54 / Ye	Diesel 1,784,454	Unknown Impressed Current	Galvanized Steel Impressed Current	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td><b>K</b></td><td>L</td></tr><tr><td><b>B</b></td><td></td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td><td></td></tr></table>	A	B	C	D	E	F	G	H	I	J	<b>K</b>	L	<b>B</b>		D	E	F	G	H	I	J	K	L		Yes Yes Yes Yes
A	B	C	D	E	F	G	H	I	J	<b>K</b>	L																					
<b>B</b>		D	E	F	G	H	I	J	K	L																						
38 / S36 Currently in Use	2766	1/1/1952 54 / Ye	Diesel 1,749,888	Unknown Impressed Current	Galvanized Steel Impressed Current	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td><b>K</b></td><td>L</td></tr><tr><td><b>B</b></td><td></td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td><td></td></tr></table>	A	B	C	D	E	F	G	H	I	J	<b>K</b>	L	<b>B</b>		D	E	F	G	H	I	J	K	L		Yes Yes Yes Yes
A	B	C	D	E	F	G	H	I	J	<b>K</b>	L																					
<b>B</b>		D	E	F	G	H	I	J	K	L																						
39 / S39 Currently In Use	2758	5/1/1997 09 / Ye	Hazardous 15,000	Unknown Impressed Current	Bare Steel Double-Walled/Non-Corro	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td><b>K</b></td><td>L</td></tr><tr><td><b>B</b></td><td></td><td>D</td><td>E</td><td>F</td><td><b>K</b></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td><td></td></tr></table>	A	B	C	D	E	F	G	H	I	J	<b>K</b>	L	<b>B</b>		D	E	F	<b>K</b>	H	I	J	K	L		Yes Yes Yes Yes
A	B	C	D	E	F	G	H	I	J	<b>K</b>	L																					
<b>B</b>		D	E	F	<b>K</b>	H	I	J	K	L																						
40 / S40 Currently In Use	2759	5/1/1997 09 / Ye	Hazardous 15,000	Unknown Impressed Current	Bare Steel Double-Walled/Non-Corro	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td><b>K</b></td><td>L</td></tr><tr><td><b>B</b></td><td></td><td>D</td><td>E</td><td>F</td><td><b>K</b></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td><td></td></tr></table>	A	B	C	D	E	F	G	H	I	J	<b>K</b>	L	<b>B</b>		D	E	F	<b>K</b>	H	I	J	K	L		Yes Yes Yes Yes
A	B	C	D	E	F	G	H	I	J	<b>K</b>	L																					
<b>B</b>		D	E	F	<b>K</b>	H	I	J	K	L																						
41 / S41 Currently In Use	2760	5/1/1997 09 / Ye	Hazardous 15,000	Unknown Impressed Current	Bare Steel Double-Walled/Non-Corro	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td><b>K</b></td><td>L</td></tr><tr><td><b>B</b></td><td></td><td>D</td><td>E</td><td>F</td><td><b>K</b></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td><td></td></tr></table>	A	B	C	D	E	F	G	H	I	J	<b>K</b>	L	<b>B</b>		D	E	F	<b>K</b>	H	I	J	K	L		Yes Yes Yes Yes
A	B	C	D	E	F	G	H	I	J	<b>K</b>	L																					
<b>B</b>		D	E	F	<b>K</b>	H	I	J	K	L																						

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Yellowstone

42 Currently In Use	/ S42	2761	5/1/1997 09 / Ye	Hazardous 15,000	Unknown Impressed Current	Bare Steel Double-Walled/Non-Corro	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td><b>K</b></td><td>L</td></tr><tr><td>B</td><td></td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td><b>L</b></td><td></td></tr></table>	A	B	C	D	E	F	G	H	I	J	<b>K</b>	L	B		D	E	F	G	H	I	J	K	<b>L</b>		Yes Yes Yes Yes
A	B	C	D	E	F	G	H	I	J	<b>K</b>	L																						
B		D	E	F	G	H	I	J	K	<b>L</b>																							
43 Currently In Use	/ S43	2762	5/1/1997 09 / Ye	Hazardous 15,000	Unknown Impressed Current	Bare Steel Double-Walled/Non-Corro	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td><b>K</b></td><td>L</td></tr><tr><td>B</td><td></td><td>D</td><td>E</td><td>F</td><td><b>K</b></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td><td></td></tr></table>	A	B	C	D	E	F	G	H	I	J	<b>K</b>	L	B		D	E	F	<b>K</b>	H	I	J	K	L		Yes Yes Yes Yes
A	B	C	D	E	F	G	H	I	J	<b>K</b>	L																						
B		D	E	F	<b>K</b>	H	I	J	K	L																							
44 Currently In Use	/ S44	2751	5/1/1997 09 / Ye	Hazardous 15,000	Unknown None	Bare Steel Double-Walled/Non-Corro	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td><b>K</b></td><td>L</td></tr><tr><td><b>K</b></td><td></td><td>D</td><td>E</td><td>F</td><td><b>K</b></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td><td></td></tr></table>	A	B	C	D	E	F	G	H	I	J	<b>K</b>	L	<b>K</b>		D	E	F	<b>K</b>	H	I	J	K	L		Yes Yes Yes Yes
A	B	C	D	E	F	G	H	I	J	<b>K</b>	L																						
<b>K</b>		D	E	F	<b>K</b>	H	I	J	K	L																							
45 Currently In Use	/ S45	2752	5/1/1997 09 / Ye	Hazardous 6,000	Unknown Impressed Current	Bare Steel Double-Walled/Non-Corro	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td><b>K</b></td><td>L</td></tr><tr><td>B</td><td></td><td>D</td><td>E</td><td>F</td><td><b>K</b></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td><td></td></tr></table>	A	B	C	D	E	F	G	H	I	J	<b>K</b>	L	B		D	E	F	<b>K</b>	H	I	J	K	L		Yes Yes Yes Yes
A	B	C	D	E	F	G	H	I	J	<b>K</b>	L																						
B		D	E	F	<b>K</b>	H	I	J	K	L																							
46 Currently In Use	/ S46	2753	5/1/1997 09 / Ye	Hazardous 6,000	Unknown Impressed Current	Bare Steel Double-Walled/Non-Corro	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td><b>K</b></td><td>L</td></tr><tr><td>B</td><td></td><td>D</td><td>E</td><td>F</td><td><b>K</b></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td><td></td></tr></table>	A	B	C	D	E	F	G	H	I	J	<b>K</b>	L	B		D	E	F	<b>K</b>	H	I	J	K	L		Yes Yes Yes Yes
A	B	C	D	E	F	G	H	I	J	<b>K</b>	L																						
B		D	E	F	<b>K</b>	H	I	J	K	L																							
47 Currently In Use	/ S47	2754	5/1/1997 09 / Ye	Hazardous 6,000	Unknown Impressed Current	Bare Steel Double-Walled/Non-Corro	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td><b>K</b></td><td>L</td></tr><tr><td>B</td><td></td><td>D</td><td>E</td><td>F</td><td><b>K</b></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td><td></td></tr></table>	A	B	C	D	E	F	G	H	I	J	<b>K</b>	L	B		D	E	F	<b>K</b>	H	I	J	K	L		Yes Yes Yes Yes
A	B	C	D	E	F	G	H	I	J	<b>K</b>	L																						
B		D	E	F	<b>K</b>	H	I	J	K	L																							
48 Currently In Use	/ S48	2755	5/1/1997 09 / Ye	Hazardous 6,000	Unknown Impressed Current	Bare Steel Double-Walled/Non-Corro	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td><b>K</b></td><td>L</td></tr><tr><td>B</td><td></td><td>D</td><td>E</td><td>F</td><td><b>K</b></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td><td></td></tr></table>	A	B	C	D	E	F	G	H	I	J	<b>K</b>	L	B		D	E	F	<b>K</b>	H	I	J	K	L		Yes Yes Yes Yes
A	B	C	D	E	F	G	H	I	J	<b>K</b>	L																						
B		D	E	F	<b>K</b>	H	I	J	K	L																							
49 Currently In Use	/ S49	2756	5/1/1997 09 / Ye	Hazardous 6,000	Unknown Impressed Current	Bare Steel Double-Walled/Non-Corro	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td><b>K</b></td><td>L</td></tr><tr><td>B</td><td></td><td>D</td><td>E</td><td>F</td><td><b>K</b></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td><td></td></tr></table>	A	B	C	D	E	F	G	H	I	J	<b>K</b>	L	B		D	E	F	<b>K</b>	H	I	J	K	L		Yes Yes Yes Yes
A	B	C	D	E	F	G	H	I	J	<b>K</b>	L																						
B		D	E	F	<b>K</b>	H	I	J	K	L																							
50 Currently In Use	/ S50	2763	5/1/1997 09 / Ye	Hazardous 6,000	Unknown Impressed Current	Galvanized Steel Double-Walled/Non-Corro	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td><b>K</b></td><td>L</td></tr><tr><td>B</td><td></td><td>D</td><td>E</td><td>F</td><td><b>K</b></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td><td></td></tr></table>	A	B	C	D	E	F	G	H	I	J	<b>K</b>	L	B		D	E	F	<b>K</b>	H	I	J	K	L		Yes Yes Yes Yes
A	B	C	D	E	F	G	H	I	J	<b>K</b>	L																						
B		D	E	F	<b>K</b>	H	I	J	K	L																							

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** Flying J Inc 1104 Country Hills Dr Ogden UT 84403 Phone: (801) 624-1295

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5612585	Flying J Inc Billings	2775 Old Hardin Road	Billings	59101	(406) 256-8826

TankID/Alt TankID	Tag Numbe	Installed	Product	Tank Mat'l of Construction	Piping Material	Piping Type	Tank Release Detection	FR Met																								
Status		Age/AST	Capacity	Secondary Option	Secondary Option		Piping Release Detection	Spill/Overl/C																								
1 / 05 Currently in Use	1109	8/1/1991 14 / No	Diesel 20,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>●</td><td>J</td><td>K</td><td>L</td></tr><tr><td>●</td><td></td><td>●</td><td>●</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	D	E	F	G	H	●	J	K	L	●		●	●	E	F	G	H	I	J	K	L	Yes Yes Yes Yes
A	B	C	D	E	F	G	H	●	J	K	L																					
●		●	●	E	F	G	H	I	J	K	L																					
2 / 04 Currently in Use	1108	8/1/1991 14 / No	Diesel 20,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>●</td><td>J</td><td>K</td><td>L</td></tr><tr><td>●</td><td></td><td>●</td><td>●</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	D	E	F	G	H	●	J	K	L	●		●	●	E	F	G	H	I	J	K	L	Yes Yes Yes Yes
A	B	C	D	E	F	G	H	●	J	K	L																					
●		●	●	E	F	G	H	I	J	K	L																					
3 / 01 Currently in Use	1105	8/1/1991 14 / No	Gasoline 12,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>●</td><td>J</td><td>K</td><td>L</td></tr><tr><td>●</td><td></td><td>●</td><td>●</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	D	E	F	G	H	●	J	K	L	●		●	●	E	F	G	H	I	J	K	L	Yes Yes Yes Yes
A	B	C	D	E	F	G	H	●	J	K	L																					
●		●	●	E	F	G	H	I	J	K	L																					
4 / 02 Currently in Use	4447	8/1/1991 14 / No	Gasoline 12,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>●</td><td>J</td><td>K</td><td>L</td></tr><tr><td>●</td><td></td><td>●</td><td>●</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	D	E	F	G	H	●	J	K	L	●		●	●	E	F	G	H	I	J	K	L	Yes Yes Yes Yes
A	B	C	D	E	F	G	H	●	J	K	L																					
●		●	●	E	F	G	H	I	J	K	L																					
5 / 06 Currently in Use	1110	8/1/1991 14 / No	Diesel 20,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>●</td><td>J</td><td>K</td><td>L</td></tr><tr><td>●</td><td></td><td>●</td><td>●</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	D	E	F	G	H	●	J	K	L	●		●	●	E	F	G	H	I	J	K	L	Yes Yes Yes Yes
A	B	C	D	E	F	G	H	●	J	K	L																					
●		●	●	E	F	G	H	I	J	K	L																					
6 / 03 Currently in Use	4448	8/1/1991 14 / No	Gasoline 12,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>●</td><td>J</td><td>K</td><td>L</td></tr><tr><td>●</td><td></td><td>●</td><td>●</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	D	E	F	G	H	●	J	K	L	●		●	●	E	F	G	H	I	J	K	L	Yes Yes Yes Yes
A	B	C	D	E	F	G	H	●	J	K	L																					
●		●	●	E	F	G	H	I	J	K	L																					

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** Overland West Inc PO Box 590 Ogden UT 84402 Phone: (801) 337-5229

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5613114	Hertz Rent A Car Airport	1901 Terminal Circle	Billings	59105	(406) 248-9151

TankID/Alt TankID	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection	Piping Release Detection	FR Met
1 / 01 Currently in Use	1780	5/1/1993 13 / No	Gasoline 8,000	Cathodically Protected Steel None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** Cenex Petroleum Inc PO Box 64089 MS 535 Saint Paul MN 55164 Phone: (651) 355-5583

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5613245	Kum and Go Store 823	2975 Grand Ave	Billings	59102	(406) 655-0871

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
1 / 03 Currently in Use	594	9/1/1993 12 / No	Diesel 12,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C D E F G H I J K L</div> <div> <input checked="" type="radio"/> <input checked="" type="radio"/> <input checked="" type="radio"/> <input checked="" type="radio"/> <input checked="" type="radio"/> <input checked="" type="radio"/> <input checked="" type="radio"/> <input checked="" type="radio"/> <input checked="" type="radio"/> <input checked="" type="radio"/> <input checked="" type="radio"/> <input checked="" type="radio"/> <input checked="" type="radio"/> <input checked="" type="radio"/> </div> </div>	Yes Yes Yes Yes
2 / 01 Currently in Use	592	9/1/1993 12 / No	Gasoline 12,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C D E F G H I J K L</div> <div> <input checked="" type="radio"/> <input checked="" type="radio"/> <input checked="" type="radio"/> <input checked="" type="radio"/> <input checked="" type="radio"/> <input checked="" type="radio"/> <input checked="" type="radio"/> <input checked="" type="radio"/> <input checked="" type="radio"/> <input checked="" type="radio"/> <input checked="" type="radio"/> <input checked="" type="radio"/> <input checked="" type="radio"/> <input checked="" type="radio"/> </div> </div>	Yes Yes Yes Yes
3 / 02 Currently in Use	593	9/1/1993 12 / No	Gasoline 12,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C D E F G H I J K L</div> <div> <input checked="" type="radio"/> <input checked="" type="radio"/> <input checked="" type="radio"/> <input checked="" type="radio"/> <input checked="" type="radio"/> <input checked="" type="radio"/> <input checked="" type="radio"/> <input checked="" type="radio"/> <input checked="" type="radio"/> <input checked="" type="radio"/> <input checked="" type="radio"/> <input checked="" type="radio"/> <input checked="" type="radio"/> <input checked="" type="radio"/> </div> </div>	Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** R L Dunker & Sons 705 Johnson Ln Billings MT 59101 Phone: (406) 252-8334

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5613600	Fly In Lube Inc	705 Johnson Ln	Billings	59101	(406) 252-8334

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
1 / S1 Currently in Use	3496	3/1/1995 11 / Ye	Other 55	Unknown None	Other Double-Walled/Non-Corro	Pressurized	<div> <div>A B C D E F G H I J K L</div> <div>B ● E F G H I J K L</div> </div>	Yes Yes Yes Yes
2 / S2 Currently in Use	3497	3/1/1995 11 / Ye	Other 55	Unknown None	Other Double-Walled/Non-Corro	Pressurized	<div> <div>A B C D E F G H I J K L</div> <div>B ● E F G H I J K L</div> </div>	Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed



## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** Fed Ex Ground Package System Inc 1000 FedEx Dr Coraopolis PA 15108 Phone: (412) 262-7347

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5613707	Fed Ex Ground Package System Inc	2575 N Frontage Road	Billings	59101	(406) 259-5744

TankID/Alt TankID	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection	Piping Release Detection	FR Met
1 / 01 Currently in Use	3370	5/1/1996 10 / No	Diesel 20,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B ● D E F ● H I J K L</div> <div>B ● E F ● H I J K L</div> </div>	<div> <div>A B ● D E F ● H I J K L</div> <div>B ● E F ● H I J K L</div> </div>	Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** Rocky Mountain Oil Co Inc 4567 W 80th St PO Box 1224 Minneapolis MN 55440 Phone: (952) 830-8891

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5613723	Holiday Stationstore 87	4041 Grand Ave	Billings	59106	(406) 651-9353

TankID/Alt TankID	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C																								
1 / 01 Currently in Use	3062	6/1/1996 10 / No	Gasoline 8,000	Polyethylene Tank Jacket Double-Walled	Flexible Plastic Double-Walled/Non-Corro	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><div></div></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td>B</td><td></td><td></td><td><div></div></td><td>E</td><td>F</td><td><div></div></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	<div></div>	E	F	G	H	I	J	K	L	B			<div></div>	E	F	<div></div>	H	I	J	K	L	Yes Yes Yes Yes
A	B	C	<div></div>	E	F	G	H	I	J	K	L																					
B			<div></div>	E	F	<div></div>	H	I	J	K	L																					
2 / 02 Currently in Use	3063	6/1/1996 10 / No	Gasoline 8,000	Polyethylene Tank Jacket Double-Walled	Flexible Plastic Double-Walled/Non-Corro	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><div></div></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td>B</td><td></td><td></td><td><div></div></td><td>E</td><td>F</td><td><div></div></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	<div></div>	E	F	G	H	I	J	K	L	B			<div></div>	E	F	<div></div>	H	I	J	K	L	Yes Yes Yes Yes
A	B	C	<div></div>	E	F	G	H	I	J	K	L																					
B			<div></div>	E	F	<div></div>	H	I	J	K	L																					
3 / 03 Currently in Use	3064	6/1/1996 10 / No	Gasoline 8,000	Polyethylene Tank Jacket Double-Walled	Flexible Plastic Double-Walled/Non-Corro	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><div></div></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td>B</td><td></td><td></td><td><div></div></td><td>E</td><td>F</td><td><div></div></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	<div></div>	E	F	G	H	I	J	K	L	B			<div></div>	E	F	<div></div>	H	I	J	K	L	Yes Yes Yes Yes
A	B	C	<div></div>	E	F	G	H	I	J	K	L																					
B			<div></div>	E	F	<div></div>	H	I	J	K	L																					
4 / 04 Currently in Use	3065	6/1/1996 10 / No	Gasoline 8,000	Polyethylene Tank Jacket Double-Walled	Flexible Plastic Double-Walled/Non-Corro	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><div></div></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td>B</td><td></td><td></td><td><div></div></td><td>E</td><td>F</td><td><div></div></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	<div></div>	E	F	G	H	I	J	K	L	B			<div></div>	E	F	<div></div>	H	I	J	K	L	Yes Yes Yes Yes
A	B	C	<div></div>	E	F	G	H	I	J	K	L																					
B			<div></div>	E	F	<div></div>	H	I	J	K	L																					
5 / 05 Currently in Use	3066	6/1/1996 10 / No	Diesel 8,000	Polyethylene Tank Jacket Double-Walled	Flexible Plastic Double-Walled/Non-Corro	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><div></div></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td>B</td><td></td><td></td><td><div></div></td><td>E</td><td>F</td><td><div></div></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	<div></div>	E	F	G	H	I	J	K	L	B			<div></div>	E	F	<div></div>	H	I	J	K	L	Yes Yes Yes Yes
A	B	C	<div></div>	E	F	G	H	I	J	K	L																					
B			<div></div>	E	F	<div></div>	H	I	J	K	L																					

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** Concept Development Corporation 523 Hilltop Road Billings MT 59105 Phone: (406) 256-1020

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5613731	Village Mart	523 Hilltop Road	Billings	59105	(406) 256-1020

TankID/Alt TankID	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction	Piping Material	Piping Type	Tank Release Detection	FR Met																										
Status				Secondary Option	Secondary Option		Piping Release Detection	Spill/Overl/C																										
1 / 01 Currently in Use	3419	7/1/1996 10 / No	Gasoline 10,000	STI-P3 None	Flexible Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td colspan="3">B</td><td colspan="3">D</td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	B			D			E	F	<input checked="" type="radio"/>	H	I	J	K	L	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																							
B			D			E	F	<input checked="" type="radio"/>	H	I	J	K	L																					
2 / 02 Currently in Use	3420	7/1/1996 10 / No	Gasoline 10,000	STI-P3 None	Flexible Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td colspan="3">B</td><td colspan="3">D</td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	B			D			E	F	<input checked="" type="radio"/>	H	I	J	K	L	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																							
B			D			E	F	<input checked="" type="radio"/>	H	I	J	K	L																					

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** Stockton Oil Co 1607 4th Ave N PO Box 1756 Billings MT 59103 Phone: (406) 245-6376

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5613741	Stockton Oil Co Shiloh Express Center	3969 Grand Ave	Billings	59102	(406) 652-0703

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
1 / 01 Currently in Use	2013	9/1/1996 09 / No	Gasoline 10,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div>	Yes Yes Yes Yes
2 / 02 Currently in Use	2014	9/1/1996 09 / No	Gasoline 20,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div>	Yes Yes Yes Yes
3 / 03 Currently in Use	2015	9/1/1996 09 / No	Gasoline 10,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div>	Yes Yes Yes Yes
4 / 04 Currently In Use	2016	9/1/1996 09 / No	Diesel 4,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div>	Yes Yes Yes Yes
5 / 05 Currently In Use	2017	9/1/1996 09 / No	Diesel 4,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div>	Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** Billings 401 Joint Venture PO Box 30238 Billings MT 59107 Phone: (406) 255-7100

<b>Sys Fac I</b>	<b>Location Name</b>	<b>Location Street Address</b>	<b>Location City</b>	<b>Zip</b>	<b>Location Phone</b>
5613766	First Interstate Bank UST	401 N 31st St	Billings	59101	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
2 / 02 Currently In Use	3400	10/1/1998 07 / No	Diesel 560	Polyethylene Tank Jacket Double-Walled	Flexible Plastic Double-Walled	Pressurized	<div style="display: flex; justify-content: space-between; padding: 2px;"> <span><input checked="" type="radio"/> B</span> <span><input type="radio"/> C</span> <span><input type="radio"/> D</span> <span><input type="radio"/> E</span> <span><input type="radio"/> F</span> <span><input checked="" type="radio"/> H</span> <span><input type="radio"/> I</span> <span><input type="radio"/> J</span> <span><input type="radio"/> K</span> <span><input type="radio"/> L</span> </div> <div style="display: flex; justify-content: space-between; padding: 2px;"> <span><input type="radio"/> B</span> <span><input type="radio"/> D</span> <span><input type="radio"/> E</span> <span><input type="radio"/> F</span> <span><input checked="" type="radio"/> H</span> <span><input type="radio"/> I</span> <span><input type="radio"/> J</span> <span><input type="radio"/> K</span> <span><input type="radio"/> L</span> </div>	Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** Billings Geyser Park LLC 4910 Southgate Dr Billings MT 59101 Phone: (406) 254-2510

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5613781	Billings Geyser Park Llc	4910 Southgate Dr	Billings	59101	(406) 254-2510

TankID/Alt TankID	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection	Piping Release Detection	FR Met
1 / 01 Currently In Use	3429	5/1/1997 09 / No	Gasoline 500	STI-P3 None	Bare Steel Cathodically Protected	Safe Suction	<input checked="" type="radio"/> A <input checked="" type="radio"/> B <input checked="" type="radio"/> C <input type="radio"/> D <input type="radio"/> E <input type="radio"/> F <input type="radio"/> G <input type="radio"/> H <input type="radio"/> I <input type="radio"/> J <input type="radio"/> K <input type="radio"/> L	<input type="radio"/> B <input type="radio"/> D <input type="radio"/> E <input type="radio"/> F <input type="radio"/> G <input type="radio"/> H <input type="radio"/> I <input checked="" type="radio"/> J <input type="radio"/> K <input type="radio"/> L	Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** GM Petroleum Dist Inc PO Box 30335 Billings MT 59107 Phone: (406) 252-4661

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5613808	Conomart Superstore 7	4903 Southgate Dr	Billings	59101	(406) 656-7775

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
1 / 01 Currently In Use	1182	12/5/1997 08 / No	Gasoline 10,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div>	Yes Yes Yes Yes
2 / 02 Currently In Use	1183	12/5/1997 08 / No	Gasoline 10,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div>	Yes Yes Yes Yes
3 / 03 Currently In Use	1184	12/5/1998 07 / No	Diesel 8,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div>	Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** Steve Ott 858 S 29th St W Billings MT 59102 Phone: (406) 656-2781

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5613884	The Wave Car Wash	858 S 29th St W	Billings	59102	(406) 656-2781

TankID/Alt TankID	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction	Piping Material	Piping Type	Tank Release Detection	FR Met																										
Status				Secondary Option	Secondary Option		Piping Release Detection	Spill/Overl/C																										
1 / 01 Currently In Use	3527	6/1/1998 08 / No	Gasoline 12,000	STI-P3 None	Flexible Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td colspan="3">B</td><td colspan="3">D</td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	B			D			E	F	<input checked="" type="radio"/>	H	I	J	K	L	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																							
B			D			E	F	<input checked="" type="radio"/>	H	I	J	K	L																					
2 / 02 Currently In Use	3528	6/1/1998 08 / No	Gasoline 12,000	STI-P3 None	Flexible Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td colspan="3">B</td><td colspan="3">D</td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	B			D			E	F	<input checked="" type="radio"/>	H	I	J	K	L	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																							
B			D			E	F	<input checked="" type="radio"/>	H	I	J	K	L																					

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed



## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** Arrow Creek Trading Post LLC 9230 Pryor Road PO Box 73 Billings MT 59101 Phone: (406) 256-1387

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5613927	Arrow Creek Trading Post LLC	9230 Pryor Road	Billings	59101	(406) 259-6342

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
1 / 01 Currently In Use	3955	3/1/1999 07 / No	Gasoline 4,000	Polyethylene Tank Jacket Double-Walled	Flexible Plastic Double-Walled	Safe Suction	<div> <div>A B C D E F G H I J K L</div> <div>B D E F G H I J K L</div> </div>	Yes Yes Yes Yes
2 / 02 Currently In Use	3956	3/1/1999 07 / No	Gasoline 8,000	Polyethylene Tank Jacket Double-Walled	Flexible Plastic Double-Walled	Safe Suction	<div> <div>A B C D E F G H I J K L</div> <div>B D E F G H I J K L</div> </div>	Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** Costco Wholesale 67 999 Lake Dr Issaquah WA 98027 Phone: (425) 427-7696

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5613953	Costco Wholesale Gasoline 69	2290 King Ave W	Billings	59102	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
1 / 01 Currently In Use	4109	10/1/1999 06 / No	Gasoline 30,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F <input checked="" type="radio"/> H I J K L</div> <div>B <input checked="" type="radio"/> E F <input checked="" type="radio"/> H I J K L</div> </div>	Yes Yes Yes Yes
2 / 02 Currently In Use	4110	10/1/1999 06 / No	Gasoline 15,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F <input checked="" type="radio"/> H I J K L</div> <div>B <input checked="" type="radio"/> E F <input checked="" type="radio"/> H I J K L</div> </div>	Yes Yes Yes Yes
3 / 03 Currently In Use	4111	10/1/1999 06 / No	Gasoline 15,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F <input checked="" type="radio"/> H I J K L</div> <div>B <input checked="" type="radio"/> E F <input checked="" type="radio"/> H I J K L</div> </div>	Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** Alscor Investors Joint Venture 10350 Bren Road W Hopkins MN 55343 Phone: (406) 245-2748

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5613972	Wells Fargo Center	175 N 27th St	Billings	59101	(406) 245-2748

TankID/Alt TankID	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
2 / 02 Currently In Use	4231	11/1/2000 05 / No	Diesel 400	STI-P3 Double-Walled	Copper Double-Walled/Non-Corro	Safe Suction	<div><div><div>A</div><div>B</div><div>C</div><div><div></div><div></div><div></div></div><div>E</div><div>F</div><div><div></div><div></div><div></div></div><div>H</div><div>I</div><div>J</div><div>K</div><div>L</div></div><div><div>B</div><div><div></div><div></div><div></div></div><div>D</div><div>E</div><div>F</div><div>G</div><div>H</div><div>I</div><div><div></div><div></div><div></div></div><div>K</div><div>L</div></div></div>	Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** Wells Fargo Bank Operations Center 2324 Overland Ave Billings MT 59102 Phone: (406) 655-7390

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5613992	Wells Fargo Bank Operations Center	2324 Overland Ave	Billings	59102	(406) 655-6680

TankID/Alt TankID	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction	Piping Material	Piping Type	Tank Release Detection	FR Met																								
Status				Secondary Option	Secondary Option		Piping Release Detection	Spill/Overl/C																								
1 / 01 Currently In Use	4279	9/1/2000 05 / No	Diesel 8,000	Polyethylene Tank Jacket Double-Walled	Flexible Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td></td><td>B</td><td></td><td>D</td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L		B		D	E	F	<input checked="" type="radio"/>	H	I	J	K	L	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L																					
	B		D	E	F	<input checked="" type="radio"/>	H	I	J	K	L																					
2 / 02 Currently In Use	4280	9/1/2000 05 / No	Diesel 8,000	Polyethylene Tank Jacket Double-Walled	Flexible Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td></td><td>B</td><td></td><td>D</td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L		B		D	E	F	<input checked="" type="radio"/>	H	I	J	K	L	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L																					
	B		D	E	F	<input checked="" type="radio"/>	H	I	J	K	L																					

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** Rocky Mountain Oil Co Inc 4567 W 80th St PO Box 1224 Minneapolis MN 55440 Phone: (952) 830-8891

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5613994	Holiday Stationstore 108	790 S Billings Blvd	Billings	59101	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
1 / 01 Currently In Use	4285	5/1/2001 05 / No	Diesel 10,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div>	Yes Yes Yes Yes
2 / 02 Currently In Use	4286	5/4/2001 05 / No	Gasoline 10,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div>	Yes Yes Yes Yes
3 / 03 Currently In Use	4287	5/1/2001 05 / No	Gasoline 10,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div>	Yes Yes Yes Yes
4 / 04 Currently In Use	4288	5/1/2001 05 / No	Gasoline 20,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div>	Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** JTL Group Inc PO Box 80066 Billings MT 59108 Phone: (406) 655-2012

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5614001	JTL Group Inc UST	1102 Shiloh Road	Billings	59106	(406) 322-2012

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
1 / 01 Currently In Use	4397	4/1/2001 05 / No	Gasoline 1,958	Polyethylene Tank Jacket Double-Walled	Fiberglass Reinforced Plastic None	Safe Suction	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F G H I <input checked="" type="radio"/> K L</div> </div>	Yes Yes Yes Yes
2 / 02 Currently In Use	4398	4/1/2001 05 / No	Diesel 13,019	Polyethylene Tank Jacket Double-Walled	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div>	Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** Billings Public Schools Dist 2      415 N 30th St   Billings   MT   59101   Phone: (406) 247-3777

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5614045	Billings Senior High School	425 Grand Ave	Billings	59101	(406) 247-2100

TankID/Alt TankID	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection	Piping Release Detection	FR Met
1 / 01 Currently In Use	4601	12/17/2001 04 / No	Diesel 3,000	STI-P3 Double-Walled	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C D E F G H I J K L</div> <div>B D E F G H I J K L</div> </div>	<div> <div>A B C D E F G H I J K L</div> <div>B D E F G H I J K L</div> </div>	Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** Billings Public Schools Dist 2      415 N 30th St   Billings   MT   59101   Phone: (406) 247-3777

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5614046	Billings West High School	2201 Saint Johns Ave	Billings	59102	(406) 655-1400

TankID/Alt TankID	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection	Piping Release Detection	FR Met
1 / 01 Currently In Use	4602	12/17/2001 04 / No	Diesel 3,000	STI-P3 Double-Walled	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C D E F <input checked="" type="radio"/> H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div>	<div> <div>A B C D E F <input checked="" type="radio"/> H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div>	Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed



## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** Lewis and Clark School 1315 Lewis Ave Billings MT 59102 Phone: (406) 255-3778

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5614070	Lewis and Clark Middle School	1315 Lewis Ave	Billings	59102	

TankID/Alt TankID	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection	Piping Release Detection	FR Met
1 / 01 Currently In Use	4970	11/15/2004 01 / No	Heating Oil 2,000	STI-P3 Double-Walled	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C D E F G H I J K L</div> <div>B D E F G H I J K L</div> </div>	<div> <div>A B C D E F G H I J K L</div> <div>B D E F G H I J K L</div> </div>	Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** Midway Motor Express 220 Orchard Ln Billings MT 59101 Phone: (406) 245-5938

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5614075	Midwest Motor Express Inc	214 Orchard Ln	Billings	59101	(406) 245-5938

TankID/Alt TankID	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection	Piping Release Detection	FR Met
1 / 01 Currently In Use	4782	1/9/2003 03 / No	Diesel 20,000	Epoxy Coated Steel Double-Walled	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div>	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div>	Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** Federal Aviation Administration 1540 Lake Elmo Dr Ste 6 Billings MT 59105 Phone: (406) 657-6981

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5614077	Billings Digital Airport Surveillance Radar	1901 Terminal Cir	Billings	59105	

TankID/Alt TankID	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection	Piping Release Detection	FR Met
1 / 01 Currently In Use	4780	12/30/2002 03 / No	Diesel 1,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	U.S. Suction	<div> <div>A B C <input checked="" type="radio"/> E F <input checked="" type="radio"/> H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div>	<div> <div>A B C <input checked="" type="radio"/> E F <input checked="" type="radio"/> H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div>	Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** New Albertsons Inc PO Box 20 Boise ID 83726 Phone: (208) 395-6200

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5614090	Albertsons Express 2038	1280 Grand Ave	Billings	59102	(406) 395-4790

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
1 / 01 Currently In Use	4844	6/24/2003 03 / No	Gasoline 15,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F <input checked="" type="radio"/> H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F <input checked="" type="radio"/> H I J K L</div> </div>	Yes Yes Yes Yes
2 / 02 Currently In Use	4845	6/24/2003 03 / No	Gasoline 10,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F <input checked="" type="radio"/> H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F <input checked="" type="radio"/> H I J K L</div> </div>	Yes Yes Yes Yes
3 / 03 Currently In Use	4846	6/24/2003 03 / No	Diesel 5,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F <input checked="" type="radio"/> H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F <input checked="" type="radio"/> H I J K L</div> </div>	Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** Hotel West II LP 1140 Reservoir Avenue Cranston RI 02920 Phone: (401) 946-4600

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5614103	Holiday Inn Billings	5500 Midland Road	Billings	59101	(406) 248-7701

TankID/Alt TankID	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection	Piping Release Detection	FR Met
3 / 02	4887	3/12/2004	Diesel	Cathodically Protected Steel	Flexible Plastic	Safe Suction	<input checked="" type="radio"/> B <input type="radio"/> C <input type="radio"/> D <input type="radio"/> E <input type="radio"/> F <input type="radio"/> G <input type="radio"/> H <input type="radio"/> I <input type="radio"/> J <input type="radio"/> K <input type="radio"/> L	<input type="radio"/> D <input type="radio"/> E <input type="radio"/> F <input type="radio"/> G <input type="radio"/> H <input type="radio"/> I <input checked="" type="radio"/> J <input type="radio"/> K <input type="radio"/> L	Yes
Currently In Use		02 / No	500	None	Secondary Containment				Yes Yes Yes

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** City of Billings Operation Center 510 N Broadway Box 1178 Billings MT 59103 Phone: (406) 657-8216

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5614118	Billings Operation Center	4848 Midland Road	Billings	59101	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
1 / 01 Currently In Use	4935	7/9/2004 01 / No	Diesel 10,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C ● E F G H ● J K L</div> <div>B D E F G H ● J K L</div> </div>	Yes Yes Yes Yes
2 / 02 Currently In Use	4936	7/9/2004 01 / No	Diesel 10,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C ● E F G H ● J K L</div> <div>B D E F G H ● J K L</div> </div>	Yes Yes Yes Yes
3 / 03 Currently In Use	4937	7/9/2004 01 / No	Gasoline 5,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C ● E F G H ● J K L</div> <div>B D E F G H ● J K L</div> </div>	Yes Yes Yes Yes
4 / 04 Currently In Use	4938	7/9/2004 01 / No	Gasoline 5,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C ● E F G H ● J K L</div> <div>B D E F G H ● J K L</div> </div>	Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** Federal Aviation Admin 1540 Lake Elmo Dr Ste 6 Billings MT 59105 Phone: (406) 657-6981

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5614127	Air Traffic Control Tower	AMT Highway 7	Billings	59105	(406) 657-6455

TankID/Alt TankID	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Over/I/C
1 / 01 Currently In Use	4976	12/9/2004 01 / No	Diesel 4,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	<div><div>A B C <input checked="" type="radio"/> E F <input checked="" type="radio"/> H I J K L</div><div>B D E F <input checked="" type="radio"/> H I <input checked="" type="radio"/> K L</div></div>	Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** School District No 2 101 10th St W Billings MT 59102 Phone:

<b>Sys Fac I</b>	<b>Location Name</b>	<b>Location Street Address</b>	<b>Location City</b>	<b>Zip</b>	<b>Location Phone</b>
5614142	Will James Middle School	1200 30th St W	Billings	59102	

TankID/Alt TankID	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
1 / 01 Currently In Use	4963	9/16/2004 01 / No	Heating Oil 2,000	STI-P3 Double-Walled	Flexible Plastic Double-Walled	Pressurized	<div style="display: flex; justify-content: space-between; font-size: 0.8em;"> <span>(A) (B) (C) (D) (E) (F) (●) (H) (I) (J) (K) (L)</span> </div> <div style="display: flex; justify-content: space-between; font-size: 0.8em;"> <span>(B) (D) (E) (F) (●) (H) (I) (J) (K) (L)</span> </div>	<div style="display: flex; justify-content: space-between; font-size: 0.8em;"> <span>Yes</span> </div> <div style="display: flex; justify-content: space-between; font-size: 0.8em;"> <span>Yes Yes Yes</span> </div>

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed



## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** School District No 2 101 10th St W Billings MT 59102 Phone:

<b>Sys Fac I</b>	<b>Location Name</b>	<b>Location Street Address</b>	<b>Location City</b>	<b>Zip</b>	<b>Location Phone</b>
5614143	Riverside Middle School	3700 Madison Ave	Billings	59101	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
1 / 01 Currently In Use	4964	9/16/2004 01 / No	Heating Oil 2,000	STI-P3 Double-Walled	Flexible Plastic Double-Walled	Pressurized	<div style="display: flex; justify-content: space-between; padding: 2px;"> <span>(A) (B) (C) (D) (E) (F) (●) (H) (I) (J) (K) (L)</span> </div> <div style="display: flex; justify-content: space-between; padding: 2px;"> <span>(B) (D) (E) (F) (●) (H) (I) (J) (K) (L)</span> </div>	Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** Town Pump Inc PO Box 6000 Butte MT 59701 Phone: (406) 497-6700

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
6015023	Town Pump Inc Billings 3	3150 King Ave W	Billings	59101	

TankID/Alt TankID	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction	Piping Material	Piping Type	Tank Release Detection	FR Met																								
Status				Secondary Option	Secondary Option		Piping Release Detection	Spill/Overl/C																								
1 / 01 Currently in Use	5062	4/14/2006 00 / No	Gasoline 20,000	Fiberglass Reinforced Plastic Double-Walled	Fiberglass Reinforced Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td colspan="2">B</td><td></td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L	B			<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L																					
B			<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L																					
2 / 02 Currently in Use	5056	4/1/2006 00 / No	Gasoline 10,000	Fiberglass Reinforced Plastic Double-Walled	Fiberglass Reinforced Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td colspan="2">B</td><td></td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L	B			<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L																					
B			<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L																					
3 / 03 Currently in Use	5057	4/6/2006 00 / No	Diesel 8,000	Fiberglass Reinforced Plastic Double-Walled	Fiberglass Reinforced Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td colspan="2">B</td><td></td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L	B			<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L																					
B			<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L																					
4 / 04 Currently in Use	5058	4/14/2006 00 / No	Diesel 10,000	Fiberglass Reinforced Plastic Double-Walled	Fiberglass Reinforced Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td colspan="2">B</td><td></td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L	B			<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L																					
B			<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L																					
5 / 05 Currently in Use	5059	4/6/2006 00 / No	Diesel 8,000	Fiberglass Reinforced Plastic Double-Walled	Fiberglass Reinforced Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td colspan="2">B</td><td></td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L	B			<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L																					
B			<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L																					
6 / 06 Currently in Use	5060	4/6/2006 00 / No	Gasoline 8,000	Fiberglass Reinforced Plastic Double-Walled	Fiberglass Reinforced Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td colspan="2">B</td><td></td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L	B			<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L																					
B			<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L																					

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** Child & Family Intervention Center 3212 First Ave S PO Box 31273 Billings MT 59101 Phone: (406) 294-9944

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
6015027	Child & Family Intervention Center	3212 First Ave S	Billings	59101	(406) 294-9944

TankID/Alt TankID	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection	Piping Release Detection	FR Met
1 / 01 Currently in Use	5072	2/6/2006 00 / No	Heating Oil 6,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	U.S. Suction	<div> <div>A B C D E F G H I J K L</div> <div>B D E F G H I J K L</div> </div>	<div> <div>A B C D E F G H I J K L</div> <div>B D E F G H I J K L</div> </div>	Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** City of Billings PO Box 1178 Billings MT 59103 Phone: (406) 657-8412

<b>Sys Fac I</b>	<b>Location Name</b>	<b>Location Street Address</b>	<b>Location City</b>	<b>Zip</b>	<b>Location Phone</b>
6015028	Daryl Apartment	114 N 26th St	Billings	59101	

<b>TankID/Alt TankID</b>	<b>Tag Numbe</b>	<b>Installed Age/AST</b>	<b>Product Capacity</b>	<b>Tank Mat'l of Construction Secondary Option</b>	<b>Piping Material Secondary Option</b>	<b>Piping Type</b>	<b>Tank Release Detection Piping Release Detection</b>	<b>FR Met Spill/Overl/C</b>
1 / 01 Currently In Use	0		Heating Oil 1,100	Unknown None	Unknown None	Gravity Feed	<div style="display: flex; justify-content: space-between; font-size: 0.8em;"> <span>(A)(B)(C)(D)(E)(F)(G)(H)(I)(J)(K)(L)</span> <span>(B)(D)(E)(F)(G)(H)(I)(J)(K)(L)</span> </div>	No No No No

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** Northwestern Corp 40 E Broadway St Butte MT 59701 Phone: (406) 497-3000

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5601431	Broadview 500 KV Substation	MT Highway 3	Broadview	59015	

TankID/Alt TankID	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection	Piping Release Detection	FR Met
1 / 3-7 Currently in Use	1686	4/30/1982 24 / No	Diesel 2,500	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Safe Suction	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div>	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div>	Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** Broadview Service Station LLC 16437 Iowa Ave & 6th St PO Box 112 Broadview MT 59015 Phone: (406) 667-2233

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5602373	Broadview Service Station LLC	16437 Iowa Ave & 6th St	Broadview	59015	(406) 667-2233

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
6 / 06 Currently in Use	3410	5/1/1996 10 / No	Gasoline 4,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
7 / 07 Currently in Use	3411	5/1/1996 10 / No	Gasoline 6,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
8 / 08 Currently in Use	3412	5/1/1996 10 / No	Diesel 4,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** Perrin Oil & Parts Inc PO Box 30 Custer MT 59024 Phone: (406) 856-4156

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5605291	Perrin Oil & Parts Inc	523 2nd St	Custer	59024	(406) 856-4156

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
5 / S5 Currently In Use	4079	7/1/1999 07 / Ye	Gasoline 5,000	Unknown None	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C D E F G H I J K L</div> <div>B D E F H I J K L</div> </div>	Yes Yes Yes Yes
6 / S6 Currently In Use	4080	7/1/1999 07 / Ye	Gasoline 12,000	Unknown None	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C D E F G H I J K L</div> <div>B D E F H I J K L</div> </div>	Yes Yes Yes Yes
7 / S7 Currently In Use	4081	7/1/1999 07 / Ye	Diesel 12,000	Unknown None	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C D E F G H I J K L</div> <div>B D E F H I J K L</div> </div>	Yes Yes Yes Yes
8 / S8 Currently In Use	4082	7/1/1999 07 / Ye	Diesel 10,000	Unknown None	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C D E F G H I J K L</div> <div>B D E F H I J K L</div> </div>	Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** Pelican Oil Co PO Box 549 Billings MT 59103 Phone: (406) 245-4531

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5600627	Express Way	135 Northern Ave	Huntley	59037	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
3 / 03 Currently In Use	3660	11/1/1998 07 / No	Gasoline 5,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
4 / 04 Currently In Use	3661	11/1/1998 07 / No	Diesel 5,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
5 / 05 Currently In Use	3662	11/1/1998 07 / No	Gasoline 10,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed



## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** Pelican Oil Co PO Box 549 Billings MT 59103 Phone: (406) 245-4531

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5600626	Pelican Truck Plaza Inc UST	11360 S Frontage Road	Laurel	59044	

TankID/Alt TankID	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction	Piping Material	Piping Type	Tank Release Detection	FR Met																								
Status				Secondary Option	Secondary Option		Piping Release Detection	Spill/Overl/C																								
1 / 05 Currently in Use	1795	5/3/1971 35 / No	Diesel 10,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Galvanized Steel Impressed Current	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td></td><td></td><td></td><td></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C		E	F	G	H	I	J	K	L					E	F	G	H	I	J	K	L	Yes Yes Yes Yes
A	B	C		E	F	G	H	I	J	K	L																					
				E	F	G	H	I	J	K	L																					
2 / 06 Currently in Use	1796	5/2/1968 38 / No	Diesel 10,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Galvanized Steel Impressed Current	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td></td><td></td><td></td><td></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C		E	F	G	H	I	J	K	L					E	F	G	H	I	J	K	L	Yes Yes Yes Yes
A	B	C		E	F	G	H	I	J	K	L																					
				E	F	G	H	I	J	K	L																					
3 / 04 Currently in Use	1794	5/2/1968 38 / No	Diesel 10,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Galvanized Steel Impressed Current	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td></td><td></td><td></td><td></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C		E	F	G	H	I	J	K	L					E	F	G	H	I	J	K	L	Yes Yes Yes Yes
A	B	C		E	F	G	H	I	J	K	L																					
				E	F	G	H	I	J	K	L																					
4 / 02 Currently in Use	1792	5/2/1968 38 / No	Gasoline 10,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Galvanized Steel Impressed Current	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td></td><td></td><td></td><td></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C		E	F	G	H	I	J	K	L					E	F	G	H	I	J	K	L	Yes Yes Yes Yes
A	B	C		E	F	G	H	I	J	K	L																					
				E	F	G	H	I	J	K	L																					
5 / 03 Currently in Use	1793	5/2/1968 38 / No	Diesel 10,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Galvanized Steel Impressed Current	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td></td><td></td><td></td><td></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C		E	F	G	H	I	J	K	L					E	F	G	H	I	J	K	L	Yes Yes Yes Yes
A	B	C		E	F	G	H	I	J	K	L																					
				E	F	G	H	I	J	K	L																					
6 / 01 Currently in Use	1791	5/2/1968 38 / No	Gasoline 6,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Galvanized Steel Impressed Current	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td></td><td></td><td></td><td></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C		E	F	G	H	I	J	K	L					E	F	G	H	I	J	K	L	Yes Yes Yes Yes
A	B	C		E	F	G	H	I	J	K	L																					
				E	F	G	H	I	J	K	L																					
7 / 07 Currently in Use	1797	5/2/1968 38 / No	Diesel 10,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Galvanized Steel Impressed Current	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td></td><td></td><td></td><td></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C		E	F	G	H	I	J	K	L					E	F	G	H	I	J	K	L	Yes Yes Yes Yes
A	B	C		E	F	G	H	I	J	K	L																					
				E	F	G	H	I	J	K	L																					

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** Johns Laurel Servicenter 201 W Main Laurel MT 59044 Phone: (406) 628-4216

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5601069	Laurel Service Center Inc UST	201 W Main St	Laurel	59044	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
1 / 08 Currently in Use	1808	4/29/1986 20 / No	Gasoline 10,000	STI-P3 Impressed Current	Fiberglass Reinforced Plastic None	Safe Suction	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F G H I <input checked="" type="radio"/> K L</div> </div>	Yes Yes Yes Yes
2 / 09 Currently in Use	1809	4/28/1988 18 / No	Gasoline 10,000	STI-P3 Impressed Current	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> D <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
10 / 10 Currently in Use	1810	4/29/1987 19 / No	Gasoline 10,000	STI-P3 None	Fiberglass Reinforced Plastic None	Safe Suction	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F G H I <input checked="" type="radio"/> K L</div> </div>	Yes Yes Yes Yes
11 / 11 Currently in Use	1811	4/28/1988 18 / No	Diesel 10,000	STI-P3 None	No Piping None	Safe Suction	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F G H I J K L</div> </div>	Yes Yes Yes Yes
12 / 12 Currently in Use	1812	4/28/1988 18 / No	Diesel 8,000	STI-P3 None	No Piping None	Safe Suction	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F G H I J K L</div> </div>	Yes Yes Yes Yes
13 / 13 Currently in Use	1813	4/28/1988 18 / No	Diesel 4,000	STI-P3 None	Fiberglass Reinforced Plastic None	Safe Suction	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F G H I <input checked="" type="radio"/> K L</div> </div>	Yes Yes Yes Yes
14 / 14 Currently in Use	1814	4/28/1988 18 / No	Gasoline 4,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> D <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
15 / 15 Currently in Use	1815	11/15/1998 07 / No	Gasoline 10,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B <input checked="" type="radio"/> D E F G H I J K L</div> </div>	Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** Town & Country Supply Association 800 E Main PO Box 367 Laurel MT 59044 Phone: (406) 628-6314

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5604497	Town & Country Supply Laurel Assn	800 E Main St	Laurel	59044	(406) 628-6314

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
1 / 12 Currently in Use	4470	2/12/1990 16 / No	Gasoline 2,000	Composite (Steel w/ FRP) None	Fiberglass Reinforced Plastic None	Pressurized	<div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div>	Yes Yes Yes Yes
2 / 10 Currently in Use	1520	2/12/1990 16 / No	Gasoline 4,000	Composite (Steel w/ FRP) None	Fiberglass Reinforced Plastic None	Pressurized	<div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div>	Yes Yes Yes Yes
3 / 11 Currently in Use	4471	2/12/1990 16 / No	Diesel 2,000	Composite (Steel w/ FRP) None	Fiberglass Reinforced Plastic None	Pressurized	<div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div>	Yes Yes Yes Yes
11 / 08 Currently in Use	1518	2/12/1990 16 / No	Gasohol 4,000	Composite (Steel w/ FRP) None	Fiberglass Reinforced Plastic None	Pressurized	<div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div>	Yes Yes Yes Yes
12 / 09 Currently in Use	4472	2/12/1990 16 / No	Diesel 4,000	Composite (Steel w/ FRP) None	Fiberglass Reinforced Plastic None	Pressurized	<div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div>	Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** Stockton Oil Co 1607 4th Ave N PO Box 1756 Billings MT 59103 Phone: (406) 245-6376

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5605083	Kwik Way 15	815 E Main St	Laurel	59044	(406) 628-9996

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
1 / 01 Currently in Use	3831	10/1/1975 30 / No	Gasoline 10,000	Asphalt Coated or Bare Steel Impressed Current	Galvanized Steel Impressed Current	Pressurized	<div> <div>A B C D E F G H I J K L</div> <div> <input checked="" type="radio"/> <input checked="" type="radio"/> <input checked="" type="radio"/> <input checked="" type="radio"/> <input checked="" type="radio"/> <input checked="" type="radio"/> <input checked="" type="radio"/> <input checked="" type="radio"/> <input checked="" type="radio"/> <input checked="" type="radio"/> <input checked="" type="radio"/> <input checked="" type="radio"/> <input checked="" type="radio"/> <input checked="" type="radio"/> </div> </div>	Yes Yes Yes Yes
2 / 02 Currently in Use	3832	10/1/1975 30 / No	Gasoline 5,200	Asphalt Coated or Bare Steel Impressed Current	Galvanized Steel Impressed Current	Pressurized	<div> <div>A B C D E F G H I J K L</div> <div> <input checked="" type="radio"/> <input checked="" type="radio"/> <input checked="" type="radio"/> <input checked="" type="radio"/> <input checked="" type="radio"/> <input checked="" type="radio"/> <input checked="" type="radio"/> <input checked="" type="radio"/> <input checked="" type="radio"/> <input checked="" type="radio"/> <input checked="" type="radio"/> <input checked="" type="radio"/> <input checked="" type="radio"/> <input checked="" type="radio"/> </div> </div>	Yes Yes Yes Yes
3 / 03 Currently in Use	3833	10/1/1975 30 / No	Gasoline 6,000	Asphalt Coated or Bare Steel Impressed Current	Galvanized Steel Impressed Current	Pressurized	<div> <div>A B C D E F G H I J K L</div> <div> <input checked="" type="radio"/> <input checked="" type="radio"/> <input checked="" type="radio"/> <input checked="" type="radio"/> <input checked="" type="radio"/> <input checked="" type="radio"/> <input checked="" type="radio"/> <input checked="" type="radio"/> <input checked="" type="radio"/> <input checked="" type="radio"/> <input checked="" type="radio"/> <input checked="" type="radio"/> <input checked="" type="radio"/> <input checked="" type="radio"/> </div> </div>	Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** GM Petroleum Dist Inc PO Box 30335 Billings MT 59107 Phone: (406) 252-4661

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5606965	Conomart Superstore 3	519 W Main St	Laurel	59044	(406) 656-7775

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
1 / 05 Currently in Use	1173	10/17/1995 10 / No	Gasoline 8,000	STI-P3 None	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div>	Yes Yes Yes Yes
2 / 06 Currently in Use	1174	10/17/1995 10 / No	Gasoline 8,000	STI-P3 None	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div>	Yes Yes Yes Yes
5 / 04 Currently in Use	1172	10/17/1995 10 / No	Gasoline 10,000	STI-P3 None	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div>	Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** GM Petroleum Dist Inc PO Box 30335 Billings MT 59107 Phone: (406) 252-4661

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5606966	Conomart Superstore 2	411 E 1st St	Laurel	59044	(406) 656-7775

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
1 / 03 Currently in Use	1177	4/22/1977 29 / No	Gasoline 10,000	Asphalt Coated or Bare Steel Lined Interior/Impressed Curr	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
2 / 02 Currently in Use	1176	4/22/1977 29 / No	Gasoline 10,000	Asphalt Coated or Bare Steel Lined Interior/Impressed Curr	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
3 / 01 Currently in Use	1175	4/22/1977 29 / No	Diesel 4,000	Asphalt Coated or Bare Steel Lined Interior/Impressed Curr	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** Town & Country Supply Association 800 E Main PO Box 367 Laurel MT 59044 Phone: (406) 628-6314

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5608161	Laurel Cenex C Store	315 S 1st Ave	Laurel	59044	(406) 628-8660

TankID/Alt TankID	Tag Numbe	Installed	Product	Tank Mat'l of Construction	Piping Material	Piping Type	Tank Release Detection	FR Met																								
Status		Age/AST	Capacity	Secondary Option	Secondary Option		Piping Release Detection	Spill/Overl/C																								
5 / 05 Currently In Use	1523	5/22/1995 11 / No	Gasohol 12,000	STI-P3 None	Flexible Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td colspan="2">B</td><td colspan="2">D</td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	B		D		E	F	<input checked="" type="radio"/>	H	I	J	K	L	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					
B		D		E	F	<input checked="" type="radio"/>	H	I	J	K	L																					
6 / 06 Currently in Use	1524	5/22/1995 11 / No	Gasoline 12,000	STI-P3 None	Flexible Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td colspan="2">B</td><td colspan="2">D</td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	B		D		E	F	<input checked="" type="radio"/>	H	I	J	K	L	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					
B		D		E	F	<input checked="" type="radio"/>	H	I	J	K	L																					
7 / 07 Currently in Use	1525	5/22/1995 11 / No	Gasoline 12,000	STI-P3 None	Flexible Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td colspan="2">B</td><td colspan="2">D</td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	B		D		E	F	<input checked="" type="radio"/>	H	I	J	K	L	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					
B		D		E	F	<input checked="" type="radio"/>	H	I	J	K	L																					
8 / 08 Currently in Use	1526	5/22/1995 11 / No	Diesel 6,000	STI-P3 None	Flexible Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td colspan="2">B</td><td colspan="2">D</td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	B		D		E	F	<input checked="" type="radio"/>	H	I	J	K	L	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					
B		D		E	F	<input checked="" type="radio"/>	H	I	J	K	L																					
9 / 09 Currently in Use	1527	5/22/1995 11 / No	Diesel 6,000	STI-P3 None	Flexible Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td colspan="2">B</td><td colspan="2">D</td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	B		D		E	F	<input checked="" type="radio"/>	H	I	J	K	L	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					
B		D		E	F	<input checked="" type="radio"/>	H	I	J	K	L																					

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** Town Pump Inc PO Box 6000 Butte MT 59701 Phone: (406) 497-6700

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5608710	Town Pump Inc Laurel	312 W 1st St	Laurel	59044	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
1 / 01 Currently in Use	2668	4/14/1974 32 / No	Gasoline 8,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Galvanized Steel Impressed Current	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
2 / 02 Currently in Use	2669	4/14/1974 32 / No	Gasoline 8,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Galvanized Steel Impressed Current	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
3 / 03 Currently in Use	2670	4/14/1974 32 / No	Gasoline 8,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Galvanized Steel Impressed Current	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
4 / 04 Currently in Use	4589	4/14/1980 26 / No	Diesel 12,000	STI-P3 None	Fiberglass Reinforced Plastic Double-Walled	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F <input checked="" type="radio"/> H I J K L</div> </div>	Yes Yes Yes Yes
5 / 05 Currently in Use	2672	4/14/1980 26 / No	Gasoline 12,000	STI-P3 Impressed Current	Flexible Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
6 / 06 Currently in Use	4603	4/1/1987 19 / No	Diesel 12,000	STI-P3 Impressed Current	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F <input checked="" type="radio"/> H I J K L</div> </div>	Yes Yes Yes Yes
7 / 07 Currently In Use	4590	6/1/2001 05 / No	Diesel 5,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F <input checked="" type="radio"/> H I J K L</div> <div><input checked="" type="radio"/> D E F <input checked="" type="radio"/> H I J K L</div> </div>	Yes Yes Yes Yes
8 / 08 Currently in Use	4591	6/1/2001 05 / No	Diesel 10,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F <input checked="" type="radio"/> H I J K L</div> <div><input checked="" type="radio"/> D E F <input checked="" type="radio"/> H I J K L</div> </div>	Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed



## Summary of Facility Information in the County of Yellowstone

9 / 09 Currently In Use	4592	6/1/2001 05 / No	Gasoline 5,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td>●</td><td>E</td><td>F</td><td>●</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td>B</td><td>D</td><td>E</td><td>F</td><td>●</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td><td></td><td></td></tr></table>	A	B	C	●	E	F	●	H	I	J	K	L	B	D	E	F	●	H	I	J	K	L			Yes Yes Yes Yes
A	B	C	●	E	F	●	H	I	J	K	L																					
B	D	E	F	●	H	I	J	K	L																							
10 / 10 Currently In Use	4593	6/1/2001 05 / No	Gasoline 10,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td>●</td><td>E</td><td>F</td><td>●</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td>B</td><td>D</td><td>E</td><td>F</td><td>●</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td><td></td><td></td></tr></table>	A	B	C	●	E	F	●	H	I	J	K	L	B	D	E	F	●	H	I	J	K	L			Yes Yes Yes Yes
A	B	C	●	E	F	●	H	I	J	K	L																					
B	D	E	F	●	H	I	J	K	L																							
11 / 11 Currently In Use	4594	8/25/2001 04 / No	Gasoline 15,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td>●</td><td>E</td><td>F</td><td>●</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td>B</td><td>D</td><td>E</td><td>F</td><td>●</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td><td></td><td></td></tr></table>	A	B	C	●	E	F	●	H	I	J	K	L	B	D	E	F	●	H	I	J	K	L			Yes Yes Yes Yes
A	B	C	●	E	F	●	H	I	J	K	L																					
B	D	E	F	●	H	I	J	K	L																							

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** Kent Potter PO Box 936 Laurel MT 59044 Phone: (406) 628-2219

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5613474	Northern Skies Aviation		Laurel	59044	(406) 628-2219

TankID/Alt TankID	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction	Piping Material	Piping Type	Tank Release Detection	FR Met																								
Status				Secondary Option	Secondary Option		Piping Release Detection	Spill/Overl/C																								
1 / 01 Currently in Use	4295	6/1/1994 12 / No	Gasoline 7,000	STI-P3 Double-Walled	Fiberglass Reinforced Plastic Double-Walled	Safe Suction	<table><tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td colspan="2">B</td><td colspan="2">D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td><input checked="" type="radio"/></td><td>K</td><td>L</td></tr></table>	A	B	C	D	E	F	<input checked="" type="radio"/>	H	I	J	K	L	B		D		E	F	G	H	I	<input checked="" type="radio"/>	K	L	Yes Yes Yes Yes
A	B	C	D	E	F	<input checked="" type="radio"/>	H	I	J	K	L																					
B		D		E	F	G	H	I	<input checked="" type="radio"/>	K	L																					
2 / 02 Currently in Use	4296	6/1/1994 12 / No	Gasoline 3,000	STI-P3 Double-Walled	Fiberglass Reinforced Plastic Double-Walled	Safe Suction	<table><tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td colspan="2">B</td><td colspan="2">D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td><input checked="" type="radio"/></td><td>K</td><td>L</td></tr></table>	A	B	C	D	E	F	<input checked="" type="radio"/>	H	I	J	K	L	B		D		E	F	G	H	I	<input checked="" type="radio"/>	K	L	Yes Yes Yes Yes
A	B	C	D	E	F	<input checked="" type="radio"/>	H	I	J	K	L																					
B		D		E	F	G	H	I	<input checked="" type="radio"/>	K	L																					

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** Farmers Union Oil Co 1545 Highway 312 Worden MT 59088 Phone: (406) 967-3100

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5602326	Farmers Union Oil Co Worden	1545 Highway 312	Worden	59088	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
1 / 04 Currently in Use	1006	11/1/1991 14 / No	Gasoline 6,000	Composite (Steel w/ FRP) None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
2 / 05 Currently in Use	1007	11/1/1991 14 / No	Gasoline 6,000	Composite (Steel w/ FRP) None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
3 / 06 Currently in Use	1008	11/1/1991 14 / No	Diesel 3,000	Composite (Steel w/ FRP) None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Yellowstone

**Owner Name and Address:** School Dist 24 1477 Ash St Worden MT 59088 Phone: (406) 967-2540

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5604326	School Dist 24	1477 Ash St	Worden	59088	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
1 / S8 Currently in Use	1897	8/30/1993 12 / No	Heating Oil 8,000	STI-P3 Double-Walled	Fiberglass Reinforced Plastic Double-Walled	U.S. Suction	<div> <div>A B C D E F G H I J K L</div> <div>B D E F G H I J K L</div> </div>	Yes Yes Yes Yes
6 / S5 Currently in Use	1894	3/18/1991 15 / No	Heating Oil 10,000	STI-P3 None	Fiberglass Reinforced Plastic Double-Walled	Pressurized	<div> <div>A B C D E F G H I J K L</div> <div>B D E F G H I J K L</div> </div>	Yes Yes Yes Yes
7 / S6 Currently in Use	1895	8/30/1993 12 / No	Heating Oil 1,000	STI-P3 Double-Walled	Fiberglass Reinforced Plastic Double-Walled	U.S. Suction	<div> <div>A B C D E F G H I J K L</div> <div>B D E F G H I J K L</div> </div>	Yes Yes Yes Yes
8 / S7 Currently in Use	1896	8/30/1993 12 / No	Heating Oil 6,000	STI-P3 Double-Walled	Flexible Plastic Double-Walled	U.S. Suction	<div> <div>A B C D E F G H I J K L</div> <div>B D E F G H I J K L</div> </div>	Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed